

| Old SIN | New SIN | Machine Type | Model | Feature | Service | GSA Annual Price |
|---------|---------|--------------|-------|---------|---------|------------------|
| 132-12 | 811212 | 719 | HC4 | | E24 | 14105.79 |
| 132-12 | 811212 | 719 | HC4 | | E95 | 9394.46 |
| 132-12 | 811212 | 719 | HC6 | | E24 | 14105.79 |
| 132-12 | 811212 | 719 | HC6 | | E95 | 9394.46 |
| 132-12 | 811212 | 719 | HC7 | | E24 | 33249.37 |
| 132-12 | 811212 | 719 | HC7 | | E95 | 22144.08 |
| 132-12 | 811212 | 724 | HC9 | | E24 | 1813.6 |
| 132-12 | 811212 | 724 | HC9 | | E95 | 1209.07 |
| 132-12 | 811212 | 724 | HCA | | E24 | 1813.6 |
| 132-12 | 811212 | 724 | HCA | | E95 | 1209.07 |
| 132-12 | 811212 | 724 | HCB | | E24 | 17128.46 |
| 132-12 | 811212 | 724 | HCB | | E95 | 11418.64 |
| 132-12 | 811212 | 793 | HC1 | | E24 | 806.05 |
| 132-12 | 811212 | 1164 | 95X | | E95 | 470.53 |
| 132-12 | 811212 | 1410 | RC2 | | E24 | 1360.2 |
| 132-12 | 811212 | 1410 | RC4 | | E24 | 1360.2 |
| 132-12 | 811212 | 1519 | 100 | | E24 | 90.68 |
| 132-12 | 811212 | 1519 | 200 | | E24 | 90.68 |
| 132-12 | 811212 | 1710 | 10U | | E24 | 2724.43 |
| 132-12 | 811212 | 1722 | 60U | | E24 | 2594.46 |
| 132-12 | 811212 | 1723 | 3RX | | E24 | 151.13 |
| 132-12 | 811212 | 1723 | 3RX | | E95 | 99.75 |
| 132-12 | 811212 | 1723 | HC1 | | E24 | 151.13 |
| 132-12 | 811212 | 1726 | HC2 | | E24 | 1486.15 |
| 132-12 | 811212 | 1726 | HC3 | | E24 | 1863.98 |
| 132-12 | 811212 | 1726 | HC4 | | E24 | 1863.98 |
| 132-12 | 811212 | 1727 | HC1 | | E24 | 725.44 |
| 132-12 | 811212 | 1733 | 1RU | | E24 | 725.44 |
| 132-12 | 811212 | 1733 | HC1 | | E24 | 725.44 |
| 132-12 | 811212 | 1735 | HC1 | | E24 | 120.91 |
| 132-12 | 811212 | 1740 | 1RU | | E24 | 906.8 |
| 132-12 | 811212 | 1740 | 710 | | E24 | 784.89 |
| 132-12 | 811212 | 1742 | 1RU | | E24 | 1167.76 |
| 132-12 | 811212 | 1742 | 90U | | E95 | 891.69 |
| 132-12 | 811212 | 1742 | 90U | | E24 | 1337.03 |
| 132-12 | 811212 | 1746 | C2A | | E24 | 604.53 |
| 132-12 | 811212 | 1746 | C2A | | E95 | 435.26 |
| 132-12 | 811212 | 1746 | C4A | | E24 | 1007.56 |
| 132-12 | 811212 | 1746 | C4A | | E95 | 725.44 |
| 132-12 | 811212 | 1746 | E2A | | E24 | 528.97 |
| 132-12 | 811212 | 1746 | E2A | | E95 | 380.86 |
| 132-12 | 811212 | 1746 | E4A | | E24 | 906.8 |
| 132-12 | 811212 | 1746 | E4A | | E95 | 652.9 |
| 132-12 | 811212 | 1750 | 511 | | E24 | 7003.53 |

| | | | | | | |
|--------|--------|------|-----|------|-----|---------|
| 132-12 | 811212 | 1750 | 522 | | E24 | 6671.03 |
| 132-12 | 811212 | 1750 | EX1 | | E24 | 3669.52 |
| 132-12 | 811212 | 1750 | EX2 | | E24 | 3393.45 |
| 132-12 | 811212 | 1812 | 81A | | E95 | 1450.88 |
| 132-12 | 811212 | 1812 | 81A | | E24 | 1882.32 |
| 132-12 | 811212 | 1812 | 81S | | E24 | 1882.32 |
| 132-12 | 811212 | 1814 | 20A | | E24 | 4358.69 |
| 132-12 | 811212 | 1814 | 52A | | E24 | 2075.57 |
| 132-12 | 811212 | 1814 | 70A | | E24 | 3528.46 |
| 132-12 | 811212 | 1814 | 70S | | E24 | 3528.46 |
| 132-12 | 811212 | 1814 | 72A | | E24 | 4358.69 |
| 132-12 | 811212 | 1814 | 72S | | E24 | 4358.69 |
| 132-12 | 811212 | 1815 | 80A | | E24 | 4172.29 |
| 132-12 | 811212 | 1815 | 82A | | E24 | 4172.29 |
| 132-12 | 811212 | 1815 | 82A | | E95 | 3004.53 |
| 132-12 | 811212 | 1815 | 84A | | E24 | 4944.08 |
| 132-12 | 811212 | 1815 | 88A | | E24 | 7845.84 |
| 132-12 | 811212 | 2005 | B16 | | E95 | 317.38 |
| 132-12 | 811212 | 2005 | B16 | | E24 | 444.33 |
| 132-12 | 811212 | 2005 | B32 | | E95 | 1481.11 |
| 132-12 | 811212 | 2005 | B5K | | E95 | 1198.99 |
| 132-12 | 811212 | 2005 | B64 | | E24 | 3050.88 |
| 132-12 | 811212 | 2005 | B64 | | E95 | 2179.35 |
| 132-12 | 811212 | 2005 | R18 | | E95 | 2887.66 |
| 132-12 | 811212 | 2026 | 416 | | E95 | 871.54 |
| 132-12 | 811212 | 2026 | 432 | | E95 | 1307.81 |
| 132-12 | 811212 | 2053 | 424 | | E95 | 180.35 |
| 132-12 | 811212 | 2053 | | 4001 | E95 | 45.34 |
| 132-12 | 811212 | 2053 | | 4002 | E95 | 114.86 |
| 132-12 | 811212 | 2053 | | 4005 | E95 | 52.39 |
| 132-12 | 811212 | 2053 | | 4011 | E95 | 423.17 |
| 132-12 | 811212 | 2053 | | 4020 | E95 | 709.32 |
| 132-12 | 811212 | 2053 | | 4111 | E95 | 404.03 |
| 132-12 | 811212 | 2073 | 700 | | E24 | 952.14 |
| 132-12 | 811212 | 2073 | 700 | | E95 | 680.1 |
| 132-12 | 811212 | 2076 | 112 | | E24 | 3526.45 |
| 132-12 | 811212 | 2076 | 112 | | E95 | 2518.89 |
| 132-12 | 811212 | 2076 | 124 | | E24 | 4937.03 |
| 132-12 | 811212 | 2076 | 124 | | E95 | 3526.45 |
| 132-12 | 811212 | 2076 | 212 | | E24 | 1625.19 |
| 132-12 | 811212 | 2076 | 212 | | E95 | 1160.71 |
| 132-12 | 811212 | 2076 | 224 | | E24 | 2844.33 |
| 132-12 | 811212 | 2076 | 224 | | E95 | 2031.23 |
| 132-12 | 811212 | 2076 | 312 | | E24 | 4937.03 |
| 132-12 | 811212 | 2076 | 312 | | E95 | 3526.45 |
| 132-12 | 811212 | 2076 | 324 | | E24 | 6911.84 |

| | | | | | | |
|--------|--------|------|-----|------|-----|---------|
| 132-12 | 811212 | 2076 | 324 | | E95 | 4937.03 |
| 132-12 | 811212 | 2076 | | 3504 | E24 | 987.41 |
| 132-12 | 811212 | 2076 | | 3504 | E95 | 705.29 |
| 132-12 | 811212 | 2076 | | 3512 | E24 | 634.76 |
| 132-12 | 811212 | 2076 | | 3512 | E95 | 453.4 |
| 132-12 | 811212 | 2076 | | 3514 | E24 | 1269.52 |
| 132-12 | 811212 | 2076 | | 3514 | E95 | 906.8 |
| 132-12 | 811212 | 2109 | | 3226 | E95 | 141.06 |
| 132-12 | 811212 | 2212 | | 3200 | E95 | 317.38 |
| 132-12 | 811212 | 2452 | 650 | | E24 | 1375.31 |
| 132-12 | 811212 | 2452 | 650 | | E95 | 982.37 |
| 132-12 | 811212 | 2452 | 680 | | E24 | 1544.58 |
| 132-12 | 811212 | 2452 | 680 | | E95 | 1103.27 |
| 132-12 | 811212 | 2452 | | 1001 | E24 | 355.67 |
| 132-12 | 811212 | 2452 | | 1001 | E95 | 253.9 |
| 132-12 | 811212 | 2452 | | 1010 | E24 | 559.19 |
| 132-12 | 811212 | 2452 | | 1010 | E95 | 398.99 |
| 132-12 | 811212 | 2498 | B24 | | E95 | 453.4 |
| 132-12 | 811212 | 2498 | B24 | | E24 | 634.76 |
| 132-12 | 811212 | 2498 | B40 | | E95 | 1088.16 |
| 132-12 | 811212 | 2498 | B80 | | E95 | 4836.27 |
| 132-12 | 811212 | 2498 | E32 | | E24 | 6770.78 |
| 132-12 | 811212 | 2498 | E32 | | E95 | 4836.27 |
| 132-12 | 811212 | 2498 | F48 | | E24 | 1523.43 |
| 132-12 | 811212 | 2498 | F48 | | E95 | 1088.16 |
| 132-12 | 811212 | 2583 | AC1 | | E24 | 201.51 |
| 132-12 | 811212 | 2583 | AC1 | | E95 | 135.01 |
| 132-12 | 811212 | 3020 | HC1 | | E24 | 806.05 |
| 132-12 | 811212 | 3151 | 310 | | E95 | 44.33 |
| 132-12 | 811212 | 3153 | BA3 | | E95 | 101.76 |
| 132-12 | 811212 | 3153 | BG3 | | E95 | 101.76 |
| 132-12 | 811212 | 3153 | BW3 | | E95 | 101.76 |
| 132-12 | 811212 | 3153 | CA3 | | E95 | 101.76 |
| 132-12 | 811212 | 3153 | CG3 | | E95 | 101.76 |
| 132-12 | 811212 | 3153 | CW3 | | E95 | 101.76 |
| 132-12 | 811212 | 3172 | | 2001 | E24 | 176.32 |
| 132-12 | 811212 | 3172 | | 2002 | E24 | 634.76 |
| 132-12 | 811212 | 3172 | | 2210 | E24 | 24.18 |
| 132-12 | 811212 | 3172 | | 2215 | E24 | 148.11 |
| 132-12 | 811212 | 3172 | | 2220 | E24 | 69.52 |
| 132-12 | 811212 | 3172 | | 2225 | E24 | 69.52 |
| 132-12 | 811212 | 3172 | | 2230 | E24 | 173.3 |
| 132-12 | 811212 | 3172 | | 2240 | E24 | 173.3 |
| 132-12 | 811212 | 3172 | | 2250 | E24 | 4088.66 |
| 132-12 | 811212 | 3172 | | 2300 | E24 | 183.38 |
| 132-12 | 811212 | 3172 | | 2310 | E24 | 207.56 |

| | | | | | | |
|--------|--------|------|-----|------|-----|---------|
| 132-12 | 811212 | 3172 | | 2501 | E24 | 69.52 |
| 132-12 | 811212 | 3172 | | 2750 | E24 | 154.16 |
| 132-12 | 811212 | 3172 | | 2752 | E24 | 126.95 |
| 132-12 | 811212 | 3172 | | 2800 | E24 | 1714.86 |
| 132-12 | 811212 | 3172 | | 2801 | E24 | 788.92 |
| 132-12 | 811212 | 3172 | | 2810 | E24 | 47.36 |
| 132-12 | 811212 | 3172 | | 2815 | E24 | 58.44 |
| 132-12 | 811212 | 3172 | | 2830 | E24 | 491.69 |
| 132-12 | 811212 | 3172 | | 2855 | E24 | 489.67 |
| 132-12 | 811212 | 3172 | | 2900 | E24 | 85.64 |
| 132-12 | 811212 | 3172 | | 2910 | E24 | 85.64 |
| 132-12 | 811212 | 3172 | | 2920 | E24 | 85.64 |
| 132-12 | 811212 | 3174 | 01L | | E24 | 235.77 |
| 132-12 | 811212 | 3174 | 01R | | E24 | 215.62 |
| 132-12 | 811212 | 3174 | 03R | | E24 | 267 |
| 132-12 | 811212 | 3174 | 11L | | E24 | 235.77 |
| 132-12 | 811212 | 3174 | 11R | | E24 | 235.77 |
| 132-12 | 811212 | 3174 | 13R | | E24 | 267 |
| 132-12 | 811212 | 3174 | 14R | | E24 | 267 |
| 132-12 | 811212 | 3174 | 21L | | E24 | 235.77 |
| 132-12 | 811212 | 3174 | 21R | | E24 | 215.62 |
| 132-12 | 811212 | 3174 | 22L | | E24 | 293.2 |
| 132-12 | 811212 | 3174 | 23R | | E24 | 293.2 |
| 132-12 | 811212 | 3174 | 24R | | E24 | 267 |
| 132-12 | 811212 | 3174 | 51R | | E24 | 182.37 |
| 132-12 | 811212 | 3174 | 53R | | E24 | 235.77 |
| 132-12 | 811212 | 3174 | 61R | | E24 | 182.37 |
| 132-12 | 811212 | 3174 | 63R | | E24 | 235.77 |
| 132-12 | 811212 | 3174 | 81R | | E24 | 151.13 |
| 132-12 | 811212 | 3174 | 81S | | E24 | 137.03 |
| 132-12 | 811212 | 3174 | 90R | | E24 | 262.97 |
| 132-12 | 811212 | 3174 | 91R | | E24 | 151.13 |
| 132-12 | 811212 | 3174 | 95R | | E24 | 239.8 |
| 132-12 | 811212 | 3174 | | 1011 | E24 | 34.26 |
| 132-12 | 811212 | 3174 | | 1012 | E24 | 68.51 |
| 132-12 | 811212 | 3174 | | 1014 | E24 | 110.83 |
| 132-12 | 811212 | 3174 | | 1016 | E24 | 147.1 |
| 132-12 | 811212 | 3174 | | 1046 | E24 | 100.76 |
| 132-12 | 811212 | 3174 | | 1048 | E24 | 100.76 |
| 132-12 | 811212 | 3174 | | 1056 | E24 | 119.9 |
| 132-12 | 811212 | 3174 | | 3020 | E24 | 119.9 |
| 132-12 | 811212 | 3174 | | 3025 | E24 | 136.02 |
| 132-12 | 811212 | 3174 | | 3026 | E24 | 136.02 |
| 132-12 | 811212 | 3174 | | 3044 | E24 | 71.54 |
| 132-12 | 811212 | 3174 | | 3045 | E24 | 71.54 |
| 132-12 | 811212 | 3174 | | 3050 | E24 | 66.5 |

| | | | | | | |
|--------|--------|------|-----|------|-----|---------|
| 132-12 | 811212 | 3174 | | 3051 | E24 | 66.5 |
| 132-12 | 811212 | 3174 | | 3053 | E24 | 66.5 |
| 132-12 | 811212 | 3174 | | 3055 | E24 | 293.2 |
| 132-12 | 811212 | 3174 | | 3100 | E24 | 98.74 |
| 132-12 | 811212 | 3174 | | 3103 | E24 | 16.12 |
| 132-12 | 811212 | 3174 | | 3105 | E24 | 73.55 |
| 132-12 | 811212 | 3174 | | 3110 | E24 | 59.45 |
| 132-12 | 811212 | 3174 | | 3680 | E24 | 20.15 |
| 132-12 | 811212 | 3174 | | 4710 | E24 | 265.99 |
| 132-12 | 811212 | 3174 | | 4730 | E24 | 336.52 |
| 132-12 | 811212 | 3174 | | 4740 | E24 | 336.52 |
| 132-12 | 811212 | 3205 | 100 | | E24 | 345.59 |
| 132-12 | 811212 | 3206 | 110 | | E24 | 142.07 |
| 132-12 | 811212 | 3206 | 11S | | E24 | 305.29 |
| 132-12 | 811212 | 3299 | 1 | | E95 | 23.17 |
| 132-12 | 811212 | 3299 | 2 | | E95 | 23.17 |
| 132-12 | 811212 | 3299 | 3 | | E95 | 27.2 |
| 132-12 | 811212 | 3361 | HC1 | | E24 | 3476.07 |
| 132-12 | 811212 | 3362 | HC1 | | E24 | 1006.55 |
| 132-12 | 811212 | 3363 | A01 | | E24 | 286.15 |
| 132-12 | 811212 | 3363 | A11 | | E24 | 286.15 |
| 132-12 | 811212 | 3476 | BA1 | | E95 | 79.6 |
| 132-12 | 811212 | 3476 | BA3 | | E95 | 79.6 |
| 132-12 | 811212 | 3476 | BG1 | | E95 | 79.6 |
| 132-12 | 811212 | 3476 | BG3 | | E95 | 79.6 |
| 132-12 | 811212 | 3476 | EA1 | | E95 | 79.6 |
| 132-12 | 811212 | 3476 | EA3 | | E95 | 79.6 |
| 132-12 | 811212 | 3476 | EG1 | | E95 | 79.6 |
| 132-12 | 811212 | 3476 | EG3 | | E95 | 79.6 |
| 132-12 | 811212 | 3488 | V43 | | E95 | 85.64 |
| 132-12 | 811212 | 3488 | V51 | | E95 | 54.41 |
| 132-12 | 811212 | 3488 | V53 | | E95 | 95.72 |
| 132-12 | 811212 | 3489 | V11 | | E95 | 40.3 |
| 132-12 | 811212 | 3489 | V13 | | E95 | 45.34 |
| 132-12 | 811212 | 3489 | V1Z | | E95 | 20.15 |
| 132-12 | 811212 | 3489 | V41 | | E95 | 60.45 |
| 132-12 | 811212 | 3489 | V43 | | E95 | 89.67 |
| 132-12 | 811212 | 3489 | V51 | | E95 | 60.45 |
| 132-12 | 811212 | 3489 | V53 | | E95 | 100.76 |
| 132-12 | 811212 | 3542 | 2RU | | E24 | 1777.33 |
| 132-12 | 811212 | 3560 | 1RU | | E24 | 784.89 |
| 132-12 | 811212 | 3572 | S3H | | E95 | 700.25 |
| 132-12 | 811212 | 3572 | S4H | | E95 | 700.25 |
| 132-12 | 811212 | 3573 | L2U | | E95 | 846.35 |
| 132-12 | 811212 | 3573 | L2U | | E24 | 1184.89 |
| 132-12 | 811212 | 3573 | L4U | | E95 | 1650.38 |

| | | | | | | |
|--------|--------|------|-----|------|-----|---------|
| 132-12 | 811212 | 3573 | L4U | | E24 | 2310.33 |
| 132-12 | 811212 | 3580 | H11 | | E95 | 1175.82 |
| 132-12 | 811212 | 3580 | H13 | | E95 | 1175.82 |
| 132-12 | 811212 | 3580 | H23 | | E95 | 889.67 |
| 132-12 | 811212 | 3580 | H3V | | E24 | 885.64 |
| 132-12 | 811212 | 3580 | H3V | | E95 | 632.75 |
| 132-12 | 811212 | 3580 | H4V | | E24 | 885.64 |
| 132-12 | 811212 | 3580 | H4V | | E95 | 632.75 |
| 132-12 | 811212 | 3580 | L11 | | E95 | 1175.82 |
| 132-12 | 811212 | 3580 | L13 | | E95 | 1175.82 |
| 132-12 | 811212 | 3580 | L23 | | E95 | 889.67 |
| 132-12 | 811212 | 3580 | L33 | | E95 | 846.35 |
| 132-12 | 811212 | 3580 | L43 | | E24 | 1364.23 |
| 132-12 | 811212 | 3580 | L43 | | E95 | 974.31 |
| 132-12 | 811212 | 3580 | S43 | | E95 | 974.31 |
| 132-12 | 811212 | 3580 | S53 | | E24 | 1364.23 |
| 132-12 | 811212 | 3580 | S53 | | E95 | 974.31 |
| 132-12 | 811212 | 3581 | F28 | | E95 | 1955.67 |
| 132-12 | 811212 | 3581 | F38 | | E95 | 1898.24 |
| 132-12 | 811212 | 3581 | H13 | | E95 | 2486.65 |
| 132-12 | 811212 | 3581 | H17 | | E95 | 2702.27 |
| 132-12 | 811212 | 3581 | H23 | | E95 | 2161.21 |
| 132-12 | 811212 | 3581 | L13 | | E95 | 2486.65 |
| 132-12 | 811212 | 3581 | L17 | | E95 | 2486.65 |
| 132-12 | 811212 | 3581 | L23 | | E95 | 1879.09 |
| 132-12 | 811212 | 3581 | L28 | | E95 | 1629.22 |
| 132-12 | 811212 | 3581 | L38 | | E95 | 1629.22 |
| 132-12 | 811212 | 3582 | L23 | | E95 | 2161.21 |
| 132-12 | 811212 | 3583 | | 8103 | E24 | 192.44 |
| 132-12 | 811212 | 3583 | | 8104 | E24 | 192.44 |
| 132-12 | 811212 | 3583 | | 8105 | E24 | 252.9 |
| 132-12 | 811212 | 3745 | 130 | | E24 | 2620.65 |
| 132-12 | 811212 | 3745 | 150 | | E24 | 2811.08 |
| 132-12 | 811212 | 3745 | 170 | | E24 | 2620.65 |
| 132-12 | 811212 | 3745 | 17A | | E24 | 2620.65 |
| 132-12 | 811212 | 3745 | 210 | | E24 | 4177.33 |
| 132-12 | 811212 | 3745 | 21A | | E24 | 4177.33 |
| 132-12 | 811212 | 3745 | 310 | | E24 | 4177.33 |
| 132-12 | 811212 | 3745 | 31A | | E24 | 4177.33 |
| 132-12 | 811212 | 3745 | 410 | | E24 | 6427.2 |
| 132-12 | 811212 | 3745 | 41A | | E24 | 6427.2 |
| 132-12 | 811212 | 3745 | 610 | | E24 | 6427.2 |
| 132-12 | 811212 | 3745 | 61A | | E24 | 6427.2 |
| 132-12 | 811212 | 3745 | | 1561 | E24 | 208.56 |
| 132-12 | 811212 | 3745 | | 1562 | E24 | 247.86 |
| 132-12 | 811212 | 3745 | | 1563 | E24 | 208.56 |

| | | | | | | |
|--------|--------|------|-----|------|-----|---------|
| 132-12 | 811212 | 3745 | | 1571 | E24 | 240.81 |
| 132-12 | 811212 | 3745 | | 1573 | E24 | 240.81 |
| 132-12 | 811212 | 3745 | | 1581 | E24 | 285.14 |
| 132-12 | 811212 | 3745 | | 4720 | E24 | 220.65 |
| 132-12 | 811212 | 3745 | | 4721 | E24 | 220.65 |
| 132-12 | 811212 | 3745 | | 4740 | E24 | 378.84 |
| 132-12 | 811212 | 3745 | | 4741 | E24 | 378.84 |
| 132-12 | 811212 | 3745 | | 4760 | E24 | 395.97 |
| 132-12 | 811212 | 3745 | | 4770 | E24 | 574.31 |
| 132-12 | 811212 | 3745 | | 4771 | E24 | 574.31 |
| 132-12 | 811212 | 3745 | | 4780 | E24 | 574.31 |
| 132-12 | 811212 | 3745 | | 4781 | E24 | 574.31 |
| 132-12 | 811212 | 3745 | | 4900 | E24 | 117.88 |
| 132-12 | 811212 | 3745 | | 4901 | E24 | 319.4 |
| 132-12 | 811212 | 3745 | | 4902 | E24 | 60.45 |
| 132-12 | 811212 | 3745 | | 4903 | E24 | 49.37 |
| 132-12 | 811212 | 3745 | | 4911 | E24 | 30.23 |
| 132-12 | 811212 | 3745 | | 4931 | E24 | 30.23 |
| 132-12 | 811212 | 3745 | | 4941 | E24 | 30.23 |
| 132-12 | 811212 | 3745 | | 4942 | E24 | 30.23 |
| 132-12 | 811212 | 3745 | | 5020 | E24 | 804.03 |
| 132-12 | 811212 | 3745 | | 5021 | E24 | 804.03 |
| 132-12 | 811212 | 3745 | | 7100 | E24 | 93.7 |
| 132-12 | 811212 | 3745 | | 7101 | E24 | 93.7 |
| 132-12 | 811212 | 3745 | | 7200 | E24 | 214.61 |
| 132-12 | 811212 | 3745 | | 7825 | E24 | 246.85 |
| 132-12 | 811212 | 3745 | | 7865 | E24 | 356.68 |
| 132-12 | 811212 | 3745 | | 8320 | E24 | 39.29 |
| 132-12 | 811212 | 3746 | 900 | | E24 | 2487.66 |
| 132-12 | 811212 | 3746 | 950 | | E24 | 2487.66 |
| 132-12 | 811212 | 3746 | A11 | | E24 | 56.42 |
| 132-12 | 811212 | 3746 | A12 | | E24 | 56.42 |
| 132-12 | 811212 | 3746 | L13 | | E24 | 56.42 |
| 132-12 | 811212 | 3746 | L14 | | E24 | 56.42 |
| 132-12 | 811212 | 3746 | | 1561 | E24 | 189.42 |
| 132-12 | 811212 | 3746 | | 1562 | E24 | 225.69 |
| 132-12 | 811212 | 3746 | | 1571 | E24 | 240.81 |
| 132-12 | 811212 | 3746 | | 1581 | E24 | 271.03 |
| 132-12 | 811212 | 3746 | | 3251 | E24 | 224.69 |
| 132-12 | 811212 | 3746 | | 3286 | E24 | 537.03 |
| 132-12 | 811212 | 3746 | | 3288 | E24 | 155.16 |
| 132-12 | 811212 | 3746 | | 3289 | E24 | 310.33 |
| 132-12 | 811212 | 3746 | | 3297 | E24 | 288.16 |
| 132-12 | 811212 | 3746 | | 3299 | E24 | 235.77 |
| 132-12 | 811212 | 3746 | | 3520 | E24 | 95.72 |
| 132-12 | 811212 | 3746 | | 4720 | E24 | 201.51 |

| | | | | | | |
|--------|--------|------|-----|------|-----|---------|
| 132-12 | 811212 | 3746 | | 4900 | E24 | 108.82 |
| 132-12 | 811212 | 3746 | | 4901 | E24 | 290.18 |
| 132-12 | 811212 | 3746 | | 4911 | E24 | 29.22 |
| 132-12 | 811212 | 3746 | | 4931 | E24 | 29.22 |
| 132-12 | 811212 | 3746 | | 4941 | E24 | 29.22 |
| 132-12 | 811212 | 3746 | | 4942 | E24 | 29.22 |
| 132-12 | 811212 | 3746 | | 5000 | E24 | 586.4 |
| 132-12 | 811212 | 3746 | | 5005 | E24 | 219.65 |
| 132-12 | 811212 | 3746 | | 5015 | E24 | 965.24 |
| 132-12 | 811212 | 3746 | | 5021 | E24 | 804.03 |
| 132-12 | 811212 | 3746 | | 5022 | E24 | 1837.78 |
| 132-12 | 811212 | 3746 | | 5050 | E24 | 197.48 |
| 132-12 | 811212 | 3746 | | 5053 | E24 | 1001.51 |
| 132-12 | 811212 | 3746 | | 5200 | E24 | 596.47 |
| 132-12 | 811212 | 3746 | | 5202 | E24 | 89.67 |
| 132-12 | 811212 | 3746 | | 5210 | E24 | 118.89 |
| 132-12 | 811212 | 3746 | | 5212 | E24 | 55.42 |
| 132-12 | 811212 | 3746 | | 5423 | E24 | 1837.78 |
| 132-12 | 811212 | 3746 | | 5501 | E24 | 196.47 |
| 132-12 | 811212 | 3746 | | 5502 | E24 | 223.68 |
| 132-12 | 811212 | 3746 | | 5522 | E24 | 482.62 |
| 132-12 | 811212 | 3746 | | 5601 | E24 | 196.47 |
| 132-12 | 811212 | 3746 | | 5602 | E24 | 439.29 |
| 132-12 | 811212 | 3746 | | 5622 | E24 | 960.2 |
| 132-12 | 811212 | 3746 | | 5713 | E24 | 98.74 |
| 132-12 | 811212 | 3746 | | 7825 | E24 | 224.69 |
| 132-12 | 811212 | 3746 | | 7865 | E24 | 325.44 |
| 132-12 | 811212 | 3758 | L32 | | E95 | 1002.52 |
| 132-12 | 811212 | 3868 | 1 | | E95 | 199.5 |
| 132-12 | 811212 | 3868 | 2 | | E95 | 199.5 |
| 132-12 | 811212 | 3868 | 3 | | E95 | 220.65 |
| 132-12 | 811212 | 3868 | 4 | | E95 | 220.65 |
| 132-12 | 811212 | 4125 | | 3101 | E24 | 100.76 |
| 132-12 | 811212 | 4190 | AC1 | | E24 | 302.27 |
| 132-12 | 811212 | 4190 | MC1 | | E24 | 302.27 |
| 132-12 | 811212 | 4192 | AC1 | | E24 | 463.48 |
| 132-12 | 811212 | 4192 | MC1 | | E24 | 463.48 |
| 132-12 | 811212 | 4193 | AC1 | | E24 | 463.48 |
| 132-12 | 811212 | 4193 | MC1 | | E24 | 463.48 |
| 132-12 | 811212 | 4194 | AC1 | | E24 | 302.27 |
| 132-12 | 811212 | 4194 | MC1 | | E24 | 302.27 |
| 132-12 | 811212 | 4251 | AC1 | | E24 | 231.74 |
| 132-12 | 811212 | 4251 | MC1 | | E24 | 231.74 |
| 132-12 | 811212 | 4252 | AC1 | | E24 | 231.74 |
| 132-12 | 811212 | 4252 | MC1 | | E24 | 231.74 |
| 132-12 | 811212 | 4362 | AC1 | | E24 | 503.78 |

| | | | | | | |
|--------|--------|------|-----|------|-----|--------|
| 132-12 | 811212 | 4362 | MC1 | | E24 | 503.78 |
| 132-12 | 811212 | 4363 | AC1 | | E24 | 503.78 |
| 132-12 | 811212 | 4363 | MC1 | | E24 | 503.78 |
| 132-12 | 811212 | 4364 | AC1 | | E24 | 503.78 |
| 132-12 | 811212 | 4364 | MC1 | | E24 | 503.78 |
| 132-12 | 811212 | 4365 | AC1 | | E24 | 503.78 |
| 132-12 | 811212 | 4365 | MC1 | | E24 | 503.78 |
| 132-12 | 811212 | 4367 | AC1 | | E24 | 221.66 |
| 132-12 | 811212 | 4367 | MC1 | | E24 | 221.66 |
| 132-12 | 811212 | 4368 | AC1 | | E24 | 221.66 |
| 132-12 | 811212 | 4368 | MC1 | | E24 | 221.66 |
| 132-12 | 811212 | 4610 | DG3 | | E95 | 106.8 |
| 132-12 | 811212 | 4610 | DG4 | | E95 | 131.99 |
| 132-12 | 811212 | 4610 | DI3 | | E95 | 106.8 |
| 132-12 | 811212 | 4610 | DI4 | | E95 | 131.99 |
| 132-12 | 811212 | 4610 | DM6 | | E24 | 110.83 |
| 132-12 | 811212 | 4610 | IF6 | | E24 | 115.87 |
| 132-12 | 811212 | 4610 | TF6 | | E95 | 85.64 |
| 132-12 | 811212 | 4610 | TF7 | | E95 | 68.51 |
| 132-12 | 811212 | 4610 | TG3 | | E24 | 145.09 |
| 132-12 | 811212 | 4610 | TG4 | | E24 | 179.34 |
| 132-12 | 811212 | 4610 | TI1 | | E24 | 152.14 |
| 132-12 | 811212 | 4610 | TI2 | | E24 | 188.41 |
| 132-12 | 811212 | 4610 | TI3 | | E24 | 145.09 |
| 132-12 | 811212 | 4610 | TI4 | | E24 | 179.34 |
| 132-12 | 811212 | 4610 | TM6 | | E24 | 115.87 |
| 132-12 | 811212 | 4610 | TM7 | | E24 | 92.7 |
| 132-12 | 811212 | 4610 | TN4 | | E24 | 207.56 |
| 132-12 | 811212 | 4610 | TO3 | | E24 | 96.73 |
| 132-12 | 811212 | 4610 | TS1 | | E24 | 231.74 |
| 132-12 | 811212 | 4610 | TS2 | | E24 | 301.26 |
| 132-12 | 811212 | 4610 | TS3 | | E24 | 220.65 |
| 132-12 | 811212 | 4610 | TS4 | | E24 | 287.15 |
| 132-12 | 811212 | 4610 | | 3201 | E24 | 38.29 |
| 132-12 | 811212 | 4610 | | 3206 | E24 | 38.29 |
| 132-12 | 811212 | 4610 | | 3324 | E24 | 51.39 |
| 132-12 | 811212 | 4610 | | 3380 | E24 | 25.19 |
| 132-12 | 811212 | 4610 | | 3381 | E24 | 25.19 |
| 132-12 | 811212 | 4610 | | 3382 | E24 | 25.19 |
| 132-12 | 811212 | 4610 | | 3383 | E24 | 25.19 |
| 132-12 | 811212 | 4610 | | 3391 | E24 | 25.19 |
| 132-12 | 811212 | 4610 | | 3392 | E24 | 25.19 |
| 132-12 | 811212 | 4610 | | 3565 | E24 | 36.27 |
| 132-12 | 811212 | 4610 | | 3575 | E24 | 28.21 |
| 132-12 | 811212 | 4610 | | 3580 | E24 | 22.17 |
| 132-12 | 811212 | 4610 | | 3845 | E24 | 52.39 |

| | | | | | | |
|--------|--------|------|-----|------|-----|----------|
| 132-12 | 811212 | 4610 | | 3850 | E24 | 52.39 |
| 132-12 | 811212 | 4610 | | 3875 | E24 | 52.39 |
| 132-12 | 811212 | 4610 | | 3935 | E24 | 92.7 |
| 132-12 | 811212 | 4610 | | 3936 | E24 | 92.7 |
| 132-12 | 811212 | 4610 | | 4780 | E24 | 25.19 |
| 132-12 | 811212 | 4610 | | 4781 | E24 | 25.19 |
| 132-12 | 811212 | 4610 | | 4880 | E24 | 25.19 |
| 132-12 | 811212 | 4610 | | 4881 | E24 | 25.19 |
| 132-12 | 811212 | 4610 | | 5950 | E24 | 27.2 |
| 132-12 | 811212 | 4610 | | 5965 | E24 | 41.31 |
| 132-12 | 811212 | 4610 | | 5970 | E24 | 41.31 |
| 132-12 | 811212 | 4610 | | 5975 | E24 | 98.74 |
| 132-12 | 811212 | 4610 | | 5980 | E24 | 98.74 |
| 132-12 | 811212 | 4667 | HC9 | | E24 | 8060.45 |
| 132-12 | 811212 | 4667 | HCD | | E24 | 50377.83 |
| 132-12 | 811212 | 4667 | HCE | | E24 | 17128.46 |
| 132-12 | 811212 | 4667 | HCM | | E24 | 2518.89 |
| 132-12 | 811212 | 4667 | HCN | | E24 | 1813.6 |
| 132-12 | 811212 | 4667 | HCP | | E24 | 1813.6 |
| 132-12 | 811212 | 4667 | HCQ | | E24 | 1813.6 |
| 132-12 | 811212 | 4668 | HC5 | | E24 | 1209.07 |
| 132-12 | 811212 | 4668 | HC6 | | E24 | 120.91 |
| 132-12 | 811212 | 4669 | HCB | | E24 | 4030.23 |
| 132-12 | 811212 | 4669 | HCL | | E24 | 1209.07 |
| 132-12 | 811212 | 4669 | HCM | | E24 | 1209.07 |
| 132-12 | 811212 | 4670 | HC9 | | E24 | 4030.23 |
| 132-12 | 811212 | 4670 | HCA | | E24 | 8060.45 |
| 132-12 | 811212 | 4670 | HCB | | E24 | 17128.46 |
| 132-12 | 811212 | 4670 | HCC | | E24 | 1511.34 |
| 132-12 | 811212 | 4670 | HCD | | E24 | 8060.45 |
| 132-12 | 811212 | 4670 | HCE | | E24 | 1511.34 |
| 132-12 | 811212 | 4670 | HCF | | E24 | 8060.45 |
| 132-12 | 811212 | 4670 | HCL | | E24 | 8060.45 |
| 132-12 | 811212 | 4670 | HCM | | E24 | 17128.46 |
| 132-12 | 811212 | 4670 | HCP | | E24 | 33249.37 |
| 132-12 | 811212 | 4670 | HCQ | | E24 | 14105.79 |
| 132-12 | 811212 | 4800 | 741 | | E24 | 165.24 |
| 132-12 | 811212 | 4800 | | 3050 | E24 | 41.31 |
| 132-12 | 811212 | 4800 | | 3057 | E24 | 41.31 |
| 132-12 | 811212 | 4800 | | 3120 | E24 | 56.42 |
| 132-12 | 811212 | 4800 | | 3124 | E24 | 51.39 |
| 132-12 | 811212 | 4800 | | 3206 | E24 | 38.29 |
| 132-12 | 811212 | 4800 | | 3315 | E24 | 22.17 |
| 132-12 | 811212 | 4800 | | 3320 | E24 | 31.23 |
| 132-12 | 811212 | 4800 | | 3323 | E24 | 69.52 |
| 132-12 | 811212 | 4800 | | 3324 | E24 | 38.29 |

| | | | | | | |
|--------|--------|------|--|------|-----|-------|
| 132-12 | 811212 | 4800 | | 3565 | E24 | 36.27 |
| 132-12 | 811212 | 4800 | | 3566 | E24 | 36.27 |
| 132-12 | 811212 | 4800 | | 3575 | E24 | 28.21 |
| 132-12 | 811212 | 4800 | | 3576 | E24 | 28.21 |
| 132-12 | 811212 | 4800 | | 3580 | E24 | 22.17 |
| 132-12 | 811212 | 4800 | | 3780 | E24 | 69.52 |
| 132-12 | 811212 | 4800 | | 3845 | E24 | 57.43 |
| 132-12 | 811212 | 4800 | | 3846 | E24 | 52.39 |
| 132-12 | 811212 | 4800 | | 3850 | E24 | 52.39 |
| 132-12 | 811212 | 4800 | | 3875 | E24 | 52.39 |
| 132-12 | 811212 | 4800 | | 3946 | E24 | 51.39 |
| 132-12 | 811212 | 4800 | | 3947 | E24 | 51.39 |
| 132-12 | 811212 | 4800 | | 3948 | E24 | 56.42 |
| 132-12 | 811212 | 4800 | | 4361 | E24 | 28.21 |
| 132-12 | 811212 | 4800 | | 4369 | E24 | 25.19 |
| 132-12 | 811212 | 4800 | | 4780 | E24 | 25.19 |
| 132-12 | 811212 | 4800 | | 4781 | E24 | 25.19 |
| 132-12 | 811212 | 4800 | | 4880 | E24 | 28.21 |
| 132-12 | 811212 | 4800 | | 4881 | E24 | 28.21 |
| 132-12 | 811212 | 4800 | | 4882 | E24 | 25.19 |
| 132-12 | 811212 | 4800 | | 5400 | E24 | 19.14 |
| 132-12 | 811212 | 4800 | | 5501 | E24 | 20.15 |
| 132-12 | 811212 | 4800 | | 5502 | E24 | 23.17 |
| 132-12 | 811212 | 4800 | | 5503 | E24 | 13.1 |
| 132-12 | 811212 | 4800 | | 5950 | E24 | 27.2 |
| 132-12 | 811212 | 4800 | | 5951 | E24 | 27.2 |
| 132-12 | 811212 | 4800 | | 5955 | E24 | 50.38 |
| 132-12 | 811212 | 4800 | | 5960 | E24 | 37.28 |
| 132-12 | 811212 | 4800 | | 5961 | E24 | 37.28 |
| 132-12 | 811212 | 4800 | | 5965 | E24 | 41.31 |
| 132-12 | 811212 | 4800 | | 5966 | E24 | 41.31 |
| 132-12 | 811212 | 4800 | | 5970 | E24 | 41.31 |
| 132-12 | 811212 | 4800 | | 5971 | E24 | 41.31 |
| 132-12 | 811212 | 4800 | | 5975 | E24 | 98.74 |
| 132-12 | 811212 | 4800 | | 5980 | E24 | 98.74 |
| 132-12 | 811212 | 4800 | | 7355 | E24 | 34.26 |
| 132-12 | 811212 | 4800 | | 7360 | E24 | 34.26 |
| 132-12 | 811212 | 4800 | | 7580 | E24 | 32.24 |
| 132-12 | 811212 | 4800 | | 7585 | E24 | 28.21 |
| 132-12 | 811212 | 4800 | | 7800 | E24 | 30.23 |
| 132-12 | 811212 | 4800 | | 7911 | E24 | 41.31 |
| 132-12 | 811212 | 4800 | | 7912 | E24 | 18.14 |
| 132-12 | 811212 | 4800 | | 7921 | E24 | 41.31 |
| 132-12 | 811212 | 4800 | | 7931 | E24 | 43.32 |
| 132-12 | 811212 | 4800 | | 7941 | E24 | 43.32 |
| 132-12 | 811212 | 4800 | | 7951 | E24 | 47.36 |

| | | | | | | |
|--------|--------|------|-----|------|-----|--------|
| 132-12 | 811212 | 4800 | | 7956 | E24 | 47.36 |
| 132-12 | 811212 | 4800 | | 7961 | E24 | 47.36 |
| 132-12 | 811212 | 4800 | | 7966 | E24 | 47.36 |
| 132-12 | 811212 | 4800 | | 7971 | E24 | 47.36 |
| 132-12 | 811212 | 4800 | | 7975 | E24 | 53.4 |
| 132-12 | 811212 | 4800 | | 7976 | E24 | 47.36 |
| 132-12 | 811212 | 4800 | | 7980 | E24 | 53.4 |
| 132-12 | 811212 | 4800 | | 7981 | E24 | 47.36 |
| 132-12 | 811212 | 4800 | | 7982 | E24 | 47.36 |
| 132-12 | 811212 | 4800 | | 7985 | E24 | 36.27 |
| 132-12 | 811212 | 4800 | | 7987 | E24 | 36.27 |
| 132-12 | 811212 | 4800 | | 7989 | E24 | 42.32 |
| 132-12 | 811212 | 4835 | 120 | | E24 | 513.85 |
| 132-12 | 811212 | 4835 | 150 | | E24 | 528.97 |
| 132-12 | 811212 | 4835 | 152 | | E24 | 561.21 |
| 132-12 | 811212 | 4835 | 153 | | E24 | 534 |
| 132-12 | 811212 | 4835 | | 2200 | E24 | 22.17 |
| 132-12 | 811212 | 4835 | | 3300 | E24 | 97.73 |
| 132-12 | 811212 | 4835 | | 3301 | E24 | 97.73 |
| 132-12 | 811212 | 4835 | | 3302 | E24 | 97.73 |
| 132-12 | 811212 | 4835 | | 4709 | E24 | 462.47 |
| 132-12 | 811212 | 4835 | | 4710 | E24 | 540.05 |
| 132-12 | 811212 | 4835 | | 4900 | E24 | 462.47 |
| 132-12 | 811212 | 4835 | | 4901 | E24 | 540.05 |
| 132-12 | 811212 | 4835 | | 5000 | E24 | 112.85 |
| 132-12 | 811212 | 4835 | | 7699 | E24 | 30.23 |
| 132-12 | 811212 | 4835 | | 7800 | E24 | 80.6 |
| 132-12 | 811212 | 4840 | 532 | | E95 | 258.94 |
| 132-12 | 811212 | 4840 | 53R | | E24 | 349.62 |
| 132-12 | 811212 | 4840 | 542 | | E95 | 283.12 |
| 132-12 | 811212 | 4840 | 54R | | E24 | 382.87 |
| 132-12 | 811212 | 4840 | 552 | | E95 | 283.12 |
| 132-12 | 811212 | 4840 | 55R | | E24 | 382.87 |
| 132-12 | 811212 | 4840 | 562 | | E95 | 365.74 |
| 132-12 | 811212 | 4840 | 56R | | E24 | 494.71 |
| 132-12 | 811212 | 4840 | 622 | | E95 | 253.9 |
| 132-12 | 811212 | 4840 | 62R | | E24 | 343.58 |
| 132-12 | 811212 | 4840 | 642 | | E95 | 455.42 |
| 132-12 | 811212 | 4840 | 64R | | E24 | 455.42 |
| 132-12 | 811212 | 4840 | 652 | | E95 | 455.42 |
| 132-12 | 811212 | 4840 | 65R | | E24 | 455.42 |
| 132-12 | 811212 | 4840 | | 1252 | E95 | 30.23 |
| 132-12 | 811212 | 4840 | | 1255 | E95 | 30.23 |
| 132-12 | 811212 | 4840 | | 1256 | E95 | 36.27 |
| 132-12 | 811212 | 4840 | | 1261 | E95 | 96.73 |
| 132-12 | 811212 | 4840 | | 1262 | E95 | 163.22 |

| | | | | | | |
|--------|--------|------|-----|------|-----|---------|
| 132-12 | 811212 | 4840 | | 1263 | E95 | 229.72 |
| 132-12 | 811212 | 4840 | | 1264 | E95 | 296.22 |
| 132-12 | 811212 | 4840 | | 1265 | E95 | 362.72 |
| 132-12 | 811212 | 4840 | | 1266 | E95 | 429.22 |
| 132-12 | 811212 | 4840 | | 1267 | E95 | 495.72 |
| 132-12 | 811212 | 4840 | | 1268 | E95 | 562.22 |
| 132-12 | 811212 | 4840 | | 3057 | E24 | 41.31 |
| 132-12 | 811212 | 4840 | | 3061 | E24 | 41.31 |
| 132-12 | 811212 | 4840 | | 3100 | E95 | 22.17 |
| 132-12 | 811212 | 4840 | | 3103 | E95 | 22.17 |
| 132-12 | 811212 | 4840 | | 4781 | E95 | 18.14 |
| 132-12 | 811212 | 4840 | | 4881 | E95 | 20.15 |
| 132-12 | 811212 | 4840 | | 5900 | E95 | 9.07 |
| 132-12 | 811212 | 4840 | | 5910 | E95 | 9.07 |
| 132-12 | 811212 | 4840 | | 5920 | E95 | 15.11 |
| 132-12 | 811212 | 4840 | | 7800 | E95 | 37.28 |
| 132-12 | 811212 | 5494 | EXT | | E24 | 322.42 |
| 132-12 | 811212 | 5821 | 10 | | E95 | 29.22 |
| 132-12 | 811212 | 5822 | 10 | | E95 | 78.59 |
| 132-12 | 811212 | 5822 | 18 | | E95 | 115.87 |
| 132-12 | 811212 | 6217 | AC1 | | E95 | 200.5 |
| 132-12 | 811212 | 6217 | MC1 | | E95 | 200.5 |
| 132-12 | 811212 | 6218 | AC1 | | E95 | 200.5 |
| 132-12 | 811212 | 6218 | MC1 | | E95 | 200.5 |
| 132-12 | 811212 | 6223 | AC1 | | E95 | 200.5 |
| 132-12 | 811212 | 6223 | MC1 | | E95 | 200.5 |
| 132-12 | 811212 | 6546 | oAZ | | E95 | 59.45 |
| 132-12 | 811212 | 7141 | AC1 | | E24 | 1813.6 |
| 132-12 | 811212 | 7141 | AC2 | | E24 | 1813.6 |
| 132-12 | 811212 | 7141 | MC1 | | E24 | 1813.6 |
| 132-12 | 811212 | 7141 | MC2 | | E24 | 1813.6 |
| 132-12 | 811212 | 7145 | AC1 | | E24 | 1209.07 |
| 132-12 | 811212 | 7145 | AC1 | | E95 | 806.05 |
| 132-12 | 811212 | 7145 | AC3 | | E24 | 1209.07 |
| 132-12 | 811212 | 7145 | AC3 | | E95 | 806.05 |
| 132-12 | 811212 | 7145 | AC4 | | E24 | 1209.07 |
| 132-12 | 811212 | 7145 | AC4 | | E95 | 806.05 |
| 132-12 | 811212 | 7145 | MC1 | | E24 | 1209.07 |
| 132-12 | 811212 | 7145 | MC1 | | E95 | 806.05 |
| 132-12 | 811212 | 7145 | MC3 | | E24 | 1209.07 |
| 132-12 | 811212 | 7145 | MC3 | | E95 | 806.05 |
| 132-12 | 811212 | 7145 | MC4 | | E24 | 1209.07 |
| 132-12 | 811212 | 7145 | MC4 | | E95 | 806.05 |
| 132-12 | 811212 | 7158 | AC1 | | E24 | 302.27 |
| 132-12 | 811212 | 7158 | AC1 | | E95 | 201.51 |
| 132-12 | 811212 | 7158 | MC1 | | E24 | 302.27 |

| | | | | | | |
|--------|--------|------|-----|------|-----|---------|
| 132-12 | 811212 | 7158 | MC1 | | E95 | 201.51 |
| 132-12 | 811212 | 7160 | AC1 | | E24 | 226.7 |
| 132-12 | 811212 | 7160 | AC1 | | E95 | 151.13 |
| 132-12 | 811212 | 7160 | MC1 | | E24 | 226.7 |
| 132-12 | 811212 | 7160 | MC1 | | E95 | 151.13 |
| 132-12 | 811212 | 7163 | AC1 | | E24 | 1309.82 |
| 132-12 | 811212 | 7163 | MC1 | | E24 | 1309.82 |
| 132-12 | 811212 | 7248 | | 4279 | E24 | 64.48 |
| 132-12 | 811212 | 7321 | AC1 | | E24 | 332.49 |
| 132-12 | 811212 | 7323 | AC1 | | E24 | 332.49 |
| 132-12 | 811212 | 7327 | AC1 | | E24 | 221.66 |
| 132-12 | 811212 | 7327 | MC1 | | E24 | 221.66 |
| 132-12 | 811212 | 7328 | AC1 | | E24 | 221.66 |
| 132-12 | 811212 | 7328 | MC1 | | E24 | 221.66 |
| 132-12 | 811212 | 7383 | AC1 | | E24 | 718.19 |
| 132-12 | 811212 | 7383 | AC1 | | E95 | 478.79 |
| 132-12 | 811212 | 7383 | MC1 | | E24 | 718.19 |
| 132-12 | 811212 | 7383 | MC1 | | E95 | 478.79 |
| 132-12 | 811212 | 7596 | | 6075 | E24 | 2098.74 |
| 132-12 | 811212 | 7596 | | 6082 | E24 | 78.59 |
| 132-12 | 811212 | 7596 | | 6186 | E24 | 78.59 |
| 132-12 | 811212 | 7596 | | 6187 | E24 | 89.67 |
| 132-12 | 811212 | 7596 | | 6261 | E24 | 88.66 |
| 132-12 | 811212 | 7596 | | 6285 | E24 | 107.81 |
| 132-12 | 811212 | 7596 | | 6433 | E24 | 184.38 |
| 132-12 | 811212 | 7596 | | 6435 | E24 | 78.59 |
| 132-12 | 811212 | 7596 | | 6440 | E24 | 184.38 |
| 132-12 | 811212 | 7596 | | 6442 | E24 | 78.59 |
| 132-12 | 811212 | 7596 | | 6446 | E24 | 1115.37 |
| 132-12 | 811212 | 7596 | | 6461 | E24 | 88.66 |
| 132-12 | 811212 | 7596 | | 6483 | E24 | 107.81 |
| 132-12 | 811212 | 7596 | | 6487 | E24 | 147.1 |
| 132-12 | 811212 | 7596 | | 6608 | E24 | 144.08 |
| 132-12 | 811212 | 7596 | | 6612 | E24 | 144.08 |
| 132-12 | 811212 | 7596 | | 6618 | E24 | 144.08 |
| 132-12 | 811212 | 7596 | | 6833 | E24 | 23.17 |
| 132-12 | 811212 | 7778 | 23X | | E24 | 604.53 |
| 132-12 | 811212 | 7778 | | 8273 | E24 | 1088.16 |
| 132-12 | 811212 | 7778 | | 8446 | E24 | 256.93 |
| 132-12 | 811212 | 7779 | BCS | | E24 | 1511.34 |
| 132-12 | 811212 | 7809 | H22 | | E24 | 302.27 |
| 132-12 | 811212 | 7825 | RC1 | | E24 | 755.67 |
| 132-12 | 811212 | 7825 | RC1 | | E95 | 503.78 |
| 132-12 | 811212 | 7831 | HC1 | | E24 | 36.27 |
| 132-12 | 811212 | 7833 | AC1 | | E24 | 332.49 |
| 132-12 | 811212 | 7836 | AC1 | | E24 | 403.02 |

| | | | | | | |
|--------|--------|------|-----|------|-----|---------|
| 132-12 | 811212 | 7836 | MC1 | | E24 | 403.02 |
| 132-12 | 811212 | 7837 | AC1 | | E24 | 403.02 |
| 132-12 | 811212 | 7837 | MC1 | | E24 | 403.02 |
| 132-12 | 811212 | 7839 | AC1 | | E24 | 680.1 |
| 132-12 | 811212 | 7839 | MC1 | | E24 | 680.1 |
| 132-12 | 811212 | 7852 | 400 | | E95 | 38.29 |
| 132-12 | 811212 | 7852 | 40Z | | E95 | 38.29 |
| 132-12 | 811212 | 7861 | 14 | | E24 | 51.39 |
| 132-12 | 811212 | 7861 | 15 | | E24 | 51.39 |
| 132-12 | 811212 | 7861 | 16 | | E24 | 51.39 |
| 132-12 | 811212 | 7861 | 24 | | E24 | 61.46 |
| 132-12 | 811212 | 7861 | 25 | | E24 | 61.46 |
| 132-12 | 811212 | 7861 | 26 | | E24 | 61.46 |
| 132-12 | 811212 | 7861 | 45 | | E24 | 112.85 |
| 132-12 | 811212 | 7861 | 46 | | E24 | 112.85 |
| 132-12 | 811212 | 7861 | 47 | | E24 | 112.85 |
| 132-12 | 811212 | 7861 | | 7953 | E24 | 16.12 |
| 132-12 | 811212 | 7863 | 10X | | E24 | 423.17 |
| 132-12 | 811212 | 7863 | 10X | | E95 | 282.12 |
| 132-12 | 811212 | 7866 | | 4127 | E95 | 46.35 |
| 132-12 | 811212 | 7868 | | 7952 | E24 | 9.07 |
| 132-12 | 811212 | 7868 | | 7953 | E24 | 14.11 |
| 132-12 | 811212 | 7870 | AC1 | | E24 | 302.27 |
| 132-12 | 811212 | 7870 | MC1 | | E24 | 302.27 |
| 132-12 | 811212 | 7873 | AC1 | | E24 | 299.24 |
| 132-12 | 811212 | 7873 | AC1 | | E95 | 199.5 |
| 132-12 | 811212 | 7873 | MC1 | | E24 | 299.24 |
| 132-12 | 811212 | 7873 | MC1 | | E95 | 199.5 |
| 132-12 | 811212 | 7875 | AC1 | | E24 | 392.95 |
| 132-12 | 811212 | 7875 | AC1 | | E95 | 261.96 |
| 132-12 | 811212 | 7875 | MC1 | | E24 | 392.95 |
| 132-12 | 811212 | 7875 | MC1 | | E95 | 261.96 |
| 132-12 | 811212 | 7891 | 73X | | E24 | 664.99 |
| 132-12 | 811212 | 7891 | 73X | | E95 | 443.32 |
| 132-12 | 811212 | 7891 | 74X | | E24 | 1007.56 |
| 132-12 | 811212 | 7891 | 74X | | E95 | 671.03 |
| 132-12 | 811212 | 7893 | 92X | | E24 | 1612.09 |
| 132-12 | 811212 | 7893 | 92X | | E95 | 1074.06 |
| 132-12 | 811212 | 7895 | 22X | | E24 | 201.51 |
| 132-12 | 811212 | 7895 | 22X | | E95 | 135.01 |
| 132-12 | 811212 | 7895 | 42X | | E24 | 534.01 |
| 132-12 | 811212 | 7895 | 42X | | E95 | 355.67 |
| 132-12 | 811212 | 7895 | | 8207 | E24 | 580.35 |
| 132-12 | 811212 | 7895 | | 8207 | E95 | 386.9 |
| 132-12 | 811212 | 7895 | | EPR1 | E24 | 403.02 |
| 132-12 | 811212 | 7895 | | EPR1 | E95 | 269.02 |

| | | | | | | |
|--------|--------|------|-----|------|-----|---------|
| 132-12 | 811212 | 7895 | | EPR2 | E24 | 1410.58 |
| 132-12 | 811212 | 7895 | | EPR2 | E95 | 940.05 |
| 132-12 | 811212 | 7895 | | EPR3 | E24 | 806.05 |
| 132-12 | 811212 | 7895 | | EPR3 | E95 | 537.03 |
| 132-12 | 811212 | 7895 | | EPR4 | E24 | 1612.09 |
| 132-12 | 811212 | 7895 | | EPR4 | E95 | 1074.06 |
| 132-12 | 811212 | 7895 | | EPR5 | E24 | 1007.56 |
| 132-12 | 811212 | 7895 | | EPR5 | E95 | 671.03 |
| 132-12 | 811212 | 7895 | | EPR6 | E24 | 2015.11 |
| 132-12 | 811212 | 7895 | | EPR6 | E95 | 1342.07 |
| 132-12 | 811212 | 7901 | AC1 | | E24 | 302.27 |
| 132-12 | 811212 | 7901 | MC1 | | E24 | 302.27 |
| 132-12 | 811212 | 7902 | AC1 | | E24 | 302.27 |
| 132-12 | 811212 | 7902 | MC1 | | E24 | 302.27 |
| 132-12 | 811212 | 7906 | AC1 | | E24 | 201.51 |
| 132-12 | 811212 | 7906 | AC1 | | E95 | 135.01 |
| 132-12 | 811212 | 7906 | MC1 | | E24 | 201.51 |
| 132-12 | 811212 | 7906 | MC1 | | E95 | 135.01 |
| 132-12 | 811212 | 7912 | AC1 | | E24 | 332.49 |
| 132-12 | 811212 | 7912 | AC1 | | E95 | 221.66 |
| 132-12 | 811212 | 7912 | MC1 | | E24 | 332.49 |
| 132-12 | 811212 | 7912 | MC1 | | E95 | 221.66 |
| 132-12 | 811212 | 7913 | HC1 | | E24 | 36.27 |
| 132-12 | 811212 | 7913 | HC1 | | E95 | 24.18 |
| 132-12 | 811212 | 7914 | AC1 | | E24 | 554.16 |
| 132-12 | 811212 | 7914 | AC1 | | E95 | 369.77 |
| 132-12 | 811212 | 7914 | MC1 | | E24 | 554.16 |
| 132-12 | 811212 | 7914 | MC1 | | E95 | 369.77 |
| 132-12 | 811212 | 7915 | AC1 | | E24 | 680.1 |
| 132-12 | 811212 | 7915 | AC1 | | E95 | 453.4 |
| 132-12 | 811212 | 7915 | MC1 | | E24 | 680.1 |
| 132-12 | 811212 | 7915 | MC1 | | E95 | 453.4 |
| 132-12 | 811212 | 7940 | AC1 | | E24 | 231.74 |
| 132-12 | 811212 | 7940 | MC1 | | E24 | 231.74 |
| 132-12 | 811212 | 7943 | AC1 | | E24 | 755.67 |
| 132-12 | 811212 | 7943 | MC1 | | E24 | 755.67 |
| 132-12 | 811212 | 7945 | AC1 | | E24 | 680.1 |
| 132-12 | 811212 | 7945 | AC1 | | E24 | 453.4 |
| 132-12 | 811212 | 7945 | MC1 | | E24 | 680.1 |
| 132-12 | 811212 | 7945 | MC1 | | E24 | 453.4 |
| 132-12 | 811212 | 7946 | AC1 | | E24 | 503.78 |
| 132-12 | 811212 | 7946 | AC1 | | E24 | 335.52 |
| 132-12 | 811212 | 7946 | MC1 | | E24 | 503.78 |
| 132-12 | 811212 | 7946 | MC1 | | E24 | 335.52 |
| 132-12 | 811212 | 7947 | AC1 | | E24 | 680.1 |
| 132-12 | 811212 | 7947 | MC1 | | E24 | 680.1 |

| | | | | | | |
|--------|--------|------|-----|------|-----|--------|
| 132-12 | 811212 | 7953 | 94X | | E24 | 302.27 |
| 132-12 | 811212 | 7953 | 94X | | E24 | 201.51 |
| 132-12 | 811212 | 7955 | 01M | | E24 | 604.53 |
| 132-12 | 811212 | 7955 | 01M | | E24 | 403.02 |
| 132-12 | 811212 | 7969 | AC1 | | E24 | 503.78 |
| 132-12 | 811212 | 7969 | MC1 | | E24 | 503.78 |
| 132-12 | 811212 | 7971 | AC1 | | E24 | 403.02 |
| 132-12 | 811212 | 7971 | MC1 | | E24 | 403.02 |
| 132-12 | 811212 | 7972 | AC1 | | E24 | 806.05 |
| 132-12 | 811212 | 7972 | MC1 | | E24 | 806.05 |
| 132-12 | 811212 | 7973 | AC1 | | E24 | 680.1 |
| 132-12 | 811212 | 7973 | MC1 | | E24 | 680.1 |
| 132-12 | 811212 | 7974 | AC1 | | E24 | 680.1 |
| 132-12 | 811212 | 7974 | MC1 | | E24 | 680.1 |
| 132-12 | 811212 | 7975 | AC1 | | E24 | 680.1 |
| 132-12 | 811212 | 7975 | MC1 | | E24 | 680.1 |
| 132-12 | 811212 | 7976 | AC1 | | E24 | 680.1 |
| 132-12 | 811212 | 7976 | MC1 | | E24 | 680.1 |
| 132-12 | 811212 | 7977 | AC1 | | E24 | 1360.2 |
| 132-12 | 811212 | 7977 | MC1 | | E24 | 1360.2 |
| 132-12 | 811212 | 7978 | AC1 | | E24 | 503.78 |
| 132-12 | 811212 | 7978 | MC1 | | E24 | 503.78 |
| 132-12 | 811212 | 7979 | 21U | | E24 | 680.1 |
| 132-12 | 811212 | 7979 | AC1 | | E24 | 680.1 |
| 132-12 | 811212 | 7979 | MC1 | | E24 | 680.1 |
| 132-12 | 811212 | 7981 | AC1 | | E24 | 403.02 |
| 132-12 | 811212 | 7981 | MC1 | | E24 | 403.02 |
| 132-12 | 811212 | 7984 | AC1 | | E24 | 503.78 |
| 132-12 | 811212 | 7984 | MC1 | | E24 | 503.78 |
| 132-12 | 811212 | 7985 | AC1 | | E24 | 680.1 |
| 132-12 | 811212 | 7985 | MC1 | | E24 | 680.1 |
| 132-12 | 811212 | 7988 | J21 | | E24 | 403.02 |
| 132-12 | 811212 | 7989 | BCH | | E24 | 685.14 |
| 132-12 | 811212 | 7989 | | 3248 | E24 | 967.25 |
| 132-12 | 811212 | 7989 | | 3248 | E95 | 644.84 |
| 132-12 | 811212 | 7989 | | 3284 | E24 | 926.95 |
| 132-12 | 811212 | 7989 | | 3284 | E95 | 617.63 |
| 132-12 | 811212 | 7995 | AC1 | | E24 | 403.02 |
| 132-12 | 811212 | 7995 | AC1 | | E95 | 269.02 |
| 132-12 | 811212 | 7995 | MC1 | | E24 | 403.02 |
| 132-12 | 811212 | 7996 | AC1 | | E24 | 226.7 |
| 132-12 | 811212 | 7996 | MC1 | | E24 | 226.7 |
| 132-12 | 811212 | 7998 | 60X | | E24 | 302.27 |
| 132-12 | 811212 | 7998 | 61X | | E24 | 302.27 |
| 132-12 | 811212 | 8014 | AC1 | | E24 | 226.7 |
| 132-12 | 811212 | 8014 | MC1 | | E24 | 226.7 |

| | | | | | | |
|--------|--------|------|-----|------|-----|---------|
| 132-12 | 811212 | 8028 | AC1 | | E24 | 226.7 |
| 132-12 | 811212 | 8028 | MC1 | | E24 | 226.7 |
| 132-12 | 811212 | 8038 | AC1 | | E24 | 201.51 |
| 132-12 | 811212 | 8038 | AC1 | | E95 | 135.01 |
| 132-12 | 811212 | 8038 | MC1 | | E24 | 201.51 |
| 132-12 | 811212 | 8038 | MC1 | | E95 | 135.01 |
| 132-12 | 811212 | 8228 | KT3 | | E24 | 91.69 |
| 132-12 | 811212 | 8230 | 1 | | E24 | 287.15 |
| 132-12 | 811212 | 8230 | 2 | | E24 | 329.47 |
| 132-12 | 811212 | 8230 | 3 | | E24 | 382.87 |
| 132-12 | 811212 | 8240 | 2 | | E24 | 1069.02 |
| 132-12 | 811212 | 8265 | | 5008 | E24 | 1639.29 |
| 132-12 | 811212 | 8265 | | 5012 | E24 | 332.49 |
| 132-12 | 811212 | 8265 | | 5102 | E24 | 380.86 |
| 132-12 | 811212 | 8265 | | 5104 | E24 | 976.32 |
| 132-12 | 811212 | 8265 | | 5208 | E24 | 1362.22 |
| 132-12 | 811212 | 8265 | | 5212 | E24 | 1756.17 |
| 132-12 | 811212 | 8265 | | 5300 | E24 | 1005.54 |
| 132-12 | 811212 | 8265 | | 5308 | E24 | 1390.43 |
| 132-12 | 811212 | 8265 | | 5312 | E24 | 1814.61 |
| 132-12 | 811212 | 8265 | | 5400 | E24 | 1005.54 |
| 132-12 | 811212 | 8265 | | 5401 | E24 | 1005.54 |
| 132-12 | 811212 | 8265 | | 5403 | E24 | 1005.54 |
| 132-12 | 811212 | 8265 | | 5602 | E24 | 1171.79 |
| 132-12 | 811212 | 8265 | | 5612 | E24 | 1171.79 |
| 132-12 | 811212 | 8265 | | 6501 | E24 | 732.49 |
| 132-12 | 811212 | 8265 | | 6502 | E24 | 732.49 |
| 132-12 | 811212 | 8265 | | 6511 | E24 | 269.02 |
| 132-12 | 811212 | 8265 | | 6512 | E24 | 537.03 |
| 132-12 | 811212 | 8265 | | 6540 | E24 | 117.88 |
| 132-12 | 811212 | 8265 | | 6543 | E24 | 97.73 |
| 132-12 | 811212 | 8265 | | 6558 | E24 | 245.84 |
| 132-12 | 811212 | 8265 | | 6559 | E24 | 234.76 |
| 132-12 | 811212 | 8265 | | 6560 | E24 | 234.76 |
| 132-12 | 811212 | 8265 | | 6561 | E24 | 351.64 |
| 132-12 | 811212 | 8265 | | 6570 | E24 | 663.98 |
| 132-12 | 811212 | 8265 | | 6571 | E24 | 663.98 |
| 132-12 | 811212 | 8265 | | 6572 | E24 | 663.98 |
| 132-12 | 811212 | 8265 | | 6573 | E24 | 663.98 |
| 132-12 | 811212 | 8265 | | 6574 | E24 | 663.98 |
| 132-12 | 811212 | 8265 | | 6575 | E24 | 663.98 |
| 132-12 | 811212 | 8265 | | 6616 | E24 | 1344.08 |
| 132-12 | 811212 | 8265 | | 6617 | E24 | 1576.83 |
| 132-12 | 811212 | 8265 | | 6670 | E24 | 773.8 |
| 132-12 | 811212 | 8265 | | 6671 | E24 | 773.8 |
| 132-12 | 811212 | 8265 | | 8707 | E24 | 62.47 |

| | | | | | | |
|--------|--------|------|--|------|-----|---------|
| 132-12 | 811212 | 8271 | | 1330 | E24 | 341.56 |
| 132-12 | 811212 | 8271 | | 1340 | E24 | 80.6 |
| 132-12 | 811212 | 8271 | | 1345 | E24 | 113.85 |
| 132-12 | 811212 | 8273 | | 7115 | E24 | 29.22 |
| 132-12 | 811212 | 8273 | | 7116 | E24 | 29.22 |
| 132-12 | 811212 | 8273 | | 7117 | E24 | 166.25 |
| 132-12 | 811212 | 8273 | | 7118 | E24 | 52.39 |
| 132-12 | 811212 | 8273 | | 7119 | E24 | 52.39 |
| 132-12 | 811212 | 8273 | | 7123 | E24 | 201.51 |
| 132-12 | 811212 | 8273 | | 7125 | E24 | 855.42 |
| 132-12 | 811212 | 8273 | | 7126 | E24 | 689.17 |
| 132-12 | 811212 | 8273 | | 7127 | E24 | 510.83 |
| 132-12 | 811212 | 8273 | | 7128 | E24 | 344.58 |
| 132-12 | 811212 | 8273 | | 7129 | E24 | 344.58 |
| 132-12 | 811212 | 8273 | | 7130 | E24 | 689.17 |
| 132-12 | 811212 | 8273 | | 7131 | E24 | 344.58 |
| 132-12 | 811212 | 8274 | | 562 | E24 | 767.76 |
| 132-12 | 811212 | 8274 | | 582 | E24 | 727.46 |
| 132-12 | 811212 | 8274 | | 583 | E24 | 706.3 |
| 132-12 | 811212 | 8274 | | 584 | E24 | 1140.55 |
| 132-12 | 811212 | 8274 | | 607 | E24 | 895.72 |
| 132-12 | 811212 | 8274 | | 867 | E24 | 869.52 |
| 132-12 | 811212 | 8274 | | 2850 | E24 | 585.39 |
| 132-12 | 811212 | 8274 | | 2993 | E24 | 162.22 |
| 132-12 | 811212 | 8274 | | 2995 | E24 | 1079.09 |
| 132-12 | 811212 | 8274 | | 2997 | E24 | 3087.15 |
| 132-12 | 811212 | 8274 | | 2999 | E24 | 1678.59 |
| 132-12 | 811212 | 8274 | | 3001 | E24 | 1950.63 |
| 132-12 | 811212 | 8274 | | 3003 | E24 | 1640.3 |
| 132-12 | 811212 | 8274 | | 3009 | E24 | 1019.65 |
| 132-12 | 811212 | 8274 | | 3013 | E24 | 1501.26 |
| 132-12 | 811212 | 8274 | | 3017 | E24 | 1345.09 |
| 132-12 | 811212 | 8274 | | 3021 | E24 | 2152.14 |
| 132-12 | 811212 | 8274 | | 3023 | E24 | 595.47 |
| 132-12 | 811212 | 8274 | | 3029 | E24 | 861.46 |
| 132-12 | 811212 | 8274 | | 3031 | E24 | 861.46 |
| 132-12 | 811212 | 8274 | | 3050 | E24 | 501.76 |
| 132-12 | 811212 | 8274 | | 3059 | E24 | 446.35 |
| 132-12 | 811212 | 8274 | | 3061 | E24 | 558.19 |
| 132-12 | 811212 | 8274 | | 3063 | E24 | 334.51 |
| 132-12 | 811212 | 8274 | | 3065 | E24 | 446.35 |
| 132-12 | 811212 | 8274 | | 3083 | E24 | 1535.52 |
| 132-12 | 811212 | 8274 | | 3169 | E24 | 797.98 |
| 132-12 | 811212 | 8274 | | 3171 | E24 | 945.09 |
| 132-12 | 811212 | 8274 | | 3725 | E24 | 767.76 |
| 132-12 | 811212 | 8274 | | 3726 | E24 | 756.67 |

| | | | | | | |
|--------|--------|------|--|------|-----|---------|
| 132-12 | 811212 | 8274 | | 3727 | E24 | 1512.34 |
| 132-12 | 811212 | 8274 | | 6863 | E24 | 686.15 |
| 132-12 | 811212 | 8274 | | 6864 | E24 | 686.15 |
| 132-12 | 811212 | 8274 | | 6865 | E24 | 508.82 |
| 132-12 | 811212 | 8274 | | 6866 | E24 | 862.47 |
| 132-12 | 811212 | 8274 | | 6867 | E24 | 261.96 |
| 132-12 | 811212 | 8274 | | 6868 | E24 | 344.58 |
| 132-12 | 811212 | 8274 | | 6869 | E24 | 512.85 |
| 132-12 | 811212 | 8274 | | 6870 | E24 | 571.28 |
| 132-12 | 811212 | 8274 | | 6871 | E24 | 562.22 |
| 132-12 | 811212 | 8274 | | 6872 | E24 | 675.06 |
| 132-12 | 811212 | 8274 | | 6873 | E24 | 797.98 |
| 132-12 | 811212 | 8274 | | 6874 | E24 | 1088.16 |
| 132-12 | 811212 | 8274 | | 6875 | E24 | 1339.04 |
| 132-12 | 811212 | 8274 | | 6876 | E24 | 1088.16 |
| 132-12 | 811212 | 8274 | | 6877 | E24 | 490.68 |
| 132-12 | 811212 | 8274 | | 6878 | E24 | 576.32 |
| 132-12 | 811212 | 8274 | | 6879 | E24 | 668.01 |
| 132-12 | 811212 | 8274 | | 6880 | E24 | 839.29 |
| 132-12 | 811212 | 8274 | | 6881 | E24 | 1336.02 |
| 132-12 | 811212 | 8274 | | 6882 | E24 | 1507.3 |
| 132-12 | 811212 | 8274 | | 6883 | E24 | 2045.34 |
| 132-12 | 811212 | 8274 | | 6884 | E24 | 2386.9 |
| 132-12 | 811212 | 8274 | | 6885 | E24 | 981.36 |
| 132-12 | 811212 | 8274 | | 6886 | E24 | 1152.64 |
| 132-12 | 811212 | 8274 | | 6887 | E24 | 1339.04 |
| 132-12 | 811212 | 8274 | | 6888 | E24 | 1674.56 |
| 132-12 | 811212 | 8274 | | 6889 | E24 | 1103.27 |
| 132-12 | 811212 | 8274 | | 6890 | E24 | 1576.83 |
| 132-12 | 811212 | 8274 | | 6891 | E24 | 1103.27 |
| 132-12 | 811212 | 8274 | | 6892 | E24 | 1576.83 |
| 132-12 | 811212 | 8274 | | 6893 | E24 | 490.68 |
| 132-12 | 811212 | 8274 | | 6894 | E24 | 668.01 |
| 132-12 | 811212 | 8274 | | 6895 | E24 | 668.01 |
| 132-12 | 811212 | 8274 | | 6896 | E24 | 668.01 |
| 132-12 | 811212 | 8274 | | 6897 | E24 | 1021.66 |
| 132-12 | 811212 | 8274 | | 7010 | E24 | 1001.51 |
| 132-12 | 811212 | 8274 | | 7012 | E24 | 778.84 |
| 132-12 | 811212 | 8274 | | 7013 | E24 | 1445.84 |
| 132-12 | 811212 | 8274 | | 7014 | E24 | 723.43 |
| 132-12 | 811212 | 8274 | | 7015 | E24 | 945.09 |
| 132-12 | 811212 | 8274 | | 7016 | E24 | 920.91 |
| 132-12 | 811212 | 8274 | | 7017 | E24 | 920.91 |
| 132-12 | 811212 | 8274 | | 7018 | E24 | 920.91 |
| 132-12 | 811212 | 8274 | | 7019 | E24 | 834.26 |
| 132-12 | 811212 | 8274 | | 7021 | E24 | 445.34 |

| | | | | | | |
|--------|--------|------|--|------|-----|---------|
| 132-12 | 811212 | 8274 | | 7024 | E24 | 869.52 |
| 132-12 | 811212 | 8274 | | 7025 | E24 | 328.46 |
| 132-12 | 811212 | 8274 | | 7026 | E24 | 668.01 |
| 132-12 | 811212 | 8274 | | 7027 | E24 | 646.85 |
| 132-12 | 811212 | 8274 | | 7028 | E24 | 646.85 |
| 132-12 | 811212 | 8274 | | 7051 | E24 | 1057.93 |
| 132-12 | 811212 | 8274 | | 7053 | E24 | 1148.61 |
| 132-12 | 811212 | 8274 | | 7057 | E24 | 469.52 |
| 132-12 | 811212 | 8274 | | 7058 | E24 | 646.85 |
| 132-12 | 811212 | 8274 | | 7060 | E24 | 646.85 |
| 132-12 | 811212 | 8274 | | 7061 | E24 | 1001.51 |
| 132-12 | 811212 | 8274 | | 7062 | E24 | 41.31 |
| 132-12 | 811212 | 8274 | | 7074 | E24 | 1146.6 |
| 132-12 | 811212 | 8274 | | 7075 | E24 | 490.68 |
| 132-12 | 811212 | 8274 | | 7076 | E24 | 1635.26 |
| 132-12 | 811212 | 8274 | | 7077 | E24 | 1295.72 |
| 132-12 | 811212 | 8274 | | 7078 | E24 | 1110.33 |
| 132-12 | 811212 | 8274 | | 7079 | E24 | 940.05 |
| 132-12 | 811212 | 8274 | | 7080 | E24 | 2346.6 |
| 132-12 | 811212 | 8274 | | 7081 | E24 | 2004.03 |
| 132-12 | 811212 | 8274 | | 7082 | E24 | 1464.99 |
| 132-12 | 811212 | 8274 | | 7083 | E24 | 1294.71 |
| 132-12 | 811212 | 8274 | | 7084 | E24 | 818.14 |
| 132-12 | 811212 | 8274 | | 7086 | E24 | 555.16 |
| 132-12 | 811212 | 8274 | | 7087 | E24 | 469.52 |
| 132-12 | 811212 | 8274 | | 7088 | E24 | 1048.87 |
| 132-12 | 811212 | 8274 | | 7089 | E24 | 1295.72 |
| 132-12 | 811212 | 8274 | | 7090 | E24 | 1048.87 |
| 132-12 | 811212 | 8274 | | 7094 | E24 | 521.91 |
| 132-12 | 811212 | 8274 | | 7096 | E24 | 467.51 |
| 132-12 | 811212 | 8274 | | 7099 | E24 | 53.4 |
| 132-12 | 811212 | 8274 | | 7100 | E24 | 30.23 |
| 132-12 | 811212 | 8274 | | 7101 | E24 | 30.23 |
| 132-12 | 811212 | 8274 | | 7102 | E24 | 171.28 |
| 132-12 | 811212 | 8274 | | 7103 | E24 | 53.4 |
| 132-12 | 811212 | 8274 | | 7104 | E24 | 53.4 |
| 132-12 | 811212 | 8274 | | 7105 | E24 | 466.5 |
| 132-12 | 811212 | 8274 | | 7106 | E24 | 821.16 |
| 132-12 | 811212 | 8274 | | 7107 | E24 | 466.5 |
| 132-12 | 811212 | 8274 | | 7108 | E24 | 466.5 |
| 132-12 | 811212 | 8274 | | 7112 | E24 | 413.1 |
| 132-12 | 811212 | 8274 | | 7113 | E24 | 307.3 |
| 132-12 | 811212 | 8274 | | 7138 | E24 | 354.66 |
| 132-12 | 811212 | 8274 | | 7139 | E24 | 296.22 |
| 132-12 | 811212 | 8274 | | 7140 | E24 | 235.77 |
| 132-12 | 811212 | 8274 | | 7141 | E24 | 296.22 |

| | | | | | | |
|--------|--------|------|----------|------|-----|---------|
| 132-12 | 811212 | 8274 | | 7142 | E24 | 207.56 |
| 132-12 | 811212 | 8274 | | 8722 | E24 | 675.06 |
| 132-12 | 811212 | 8274 | | 8723 | E24 | 718.39 |
| 132-12 | 811212 | 8274 | | 8724 | E24 | 728.46 |
| 132-12 | 811212 | 8274 | | 8725 | E24 | 767.76 |
| 132-12 | 811212 | 8274 | | 8726 | E24 | 965.24 |
| 132-12 | 811212 | 8274 | | 8727 | E24 | 1004.53 |
| 132-12 | 811212 | 8274 | | 9582 | E24 | 1260.45 |
| 132-12 | 811212 | 8274 | | 9588 | E24 | 1260.45 |
| 132-12 | 811212 | 8274 | | 9590 | E24 | 1033.75 |
| 132-12 | 811212 | 8285 | | 5502 | E24 | 1446.85 |
| 132-12 | 811212 | 8406 | 70Y | | E24 | 428.21 |
| 132-12 | 811212 | 8406 | 71Y | | E24 | 806.05 |
| 132-12 | 811212 | 8406 | | 8358 | E24 | 201.51 |
| 132-12 | 811212 | 8485 | AC1 | | E24 | 503.78 |
| 132-12 | 811212 | 8485 | MC1 | | E24 | 503.78 |
| 132-12 | 811212 | 8486 | AC1 | | E24 | 226.7 |
| 132-12 | 811212 | 8486 | MC1 | | E24 | 226.7 |
| 132-12 | 811212 | 8488 | AC1 | | E24 | 503.78 |
| 132-12 | 811212 | 8488 | MC1 | | E24 | 503.78 |
| 132-12 | 811212 | 8490 | AC1 | | E24 | 503.78 |
| 132-12 | 811212 | 8490 | MC1 | | E24 | 503.78 |
| 132-12 | 811212 | 8491 | AC1 | | E24 | 503.78 |
| 132-12 | 811212 | 8491 | MC1 | | E24 | 503.78 |
| 132-12 | 811212 | 8639 | 0.00E+00 | | E24 | 503.78 |
| 132-12 | 811212 | 8640 | 11Y | | E24 | 1556.67 |
| 132-12 | 811212 | 8640 | 1Y0 | | E24 | 1556.67 |
| 132-12 | 811212 | 8640 | PBo | | E24 | 1556.67 |
| 132-12 | 811212 | 8648 | AC1 | | E24 | 503.78 |
| 132-12 | 811212 | 8648 | MC1 | | E24 | 503.78 |
| 132-12 | 811212 | 8651 | RM0 | | E24 | 1511.33 |
| 132-12 | 811212 | 8656 | 2RY | | E24 | 1511.33 |
| 132-12 | 811212 | 8656 | 4RY | | E24 | 1511.33 |
| 132-12 | 811212 | 8656 | 6RY | | E24 | 1511.33 |
| 132-12 | 811212 | 8660 | 42U | | E24 | 1556.67 |
| 132-12 | 811212 | 8669 | 1RX | | E24 | 680.1 |
| 132-12 | 811212 | 8669 | 4RX | | E24 | 680.1 |
| 132-12 | 811212 | 8677 | 2XX | | E24 | 685.14 |
| 132-12 | 811212 | 8677 | 3RU | | E24 | 685.14 |
| 132-12 | 811212 | 8677 | 3RU | | E95 | 456.42 |
| 132-12 | 811212 | 8677 | 3XU | | E24 | 685.14 |
| 132-12 | 811212 | 8677 | 3XU | | E95 | 456.42 |
| 132-12 | 811212 | 8677 | HC1 | | E24 | 685.14 |
| 132-12 | 811212 | 8682 | 5RY | | E24 | 1511.34 |
| 132-12 | 811212 | 8686 | 1RX | | E24 | 806.05 |
| 132-12 | 811212 | 8686 | 8RX | | E24 | 806.05 |

| | | | | | | |
|--------|--------|------|-----|--|-----|---------|
| 132-12 | 811212 | 8687 | 6RX | | E24 | 1707.81 |
| 132-12 | 811212 | 8720 | HC1 | | E24 | 685.14 |
| 132-12 | 811212 | 8721 | HC1 | | E24 | 1612.09 |
| 132-12 | 811212 | 8721 | HC1 | | E95 | 1075.06 |
| 132-12 | 811212 | 8722 | AC1 | | E24 | 1133.5 |
| 132-12 | 811212 | 8722 | AC1 | | E95 | 755.67 |
| 132-12 | 811212 | 8722 | MC1 | | E24 | 1133.5 |
| 132-12 | 811212 | 8722 | MC1 | | E95 | 755.67 |
| 132-12 | 811212 | 8730 | HC1 | | E24 | 685.14 |
| 132-12 | 811212 | 8731 | AC1 | | E24 | 604.53 |
| 132-12 | 811212 | 8731 | AC1 | | E95 | 403.02 |
| 132-12 | 811212 | 8737 | AC1 | | E24 | 423.17 |
| 132-12 | 811212 | 8737 | AC1 | | E95 | 282.12 |
| 132-12 | 811212 | 8737 | MC1 | | E24 | 423.17 |
| 132-12 | 811212 | 8737 | MC1 | | E95 | 282.12 |
| 132-12 | 811212 | 8740 | HC1 | | E24 | 685.14 |
| 132-12 | 811212 | 8750 | HC1 | | E24 | 685.14 |
| 132-12 | 811212 | 8832 | G1X | | E24 | 403.02 |
| 132-12 | 811212 | 8832 | L1X | | E24 | 403.02 |
| 132-12 | 811212 | 8832 | M1X | | E24 | 403.02 |
| 132-12 | 811212 | 8832 | M1X | | E95 | 269.02 |
| 132-12 | 811212 | 8837 | AC1 | | E24 | 503.78 |
| 132-12 | 811212 | 8837 | AC1 | | E95 | 335.52 |
| 132-12 | 811212 | 8839 | 61X | | E24 | 403.02 |
| 132-12 | 811212 | 8839 | 61X | | E95 | 269.02 |
| 132-12 | 811212 | 8840 | 25U | | E24 | 680.1 |
| 132-12 | 811212 | 8840 | 55U | | E24 | 680.1 |
| 132-12 | 811212 | 8840 | AC1 | | E24 | 680.1 |
| 132-12 | 811212 | 8840 | MC1 | | E24 | 680.1 |
| 132-12 | 811212 | 8841 | AC1 | | E24 | 1360.2 |
| 132-12 | 811212 | 8841 | MC1 | | E24 | 1360.2 |
| 132-12 | 811212 | 8843 | 21U | | E24 | 403.02 |
| 132-12 | 811212 | 8843 | 21U | | E95 | 269.02 |
| 132-12 | 811212 | 8843 | 35U | | E24 | 403.02 |
| 132-12 | 811212 | 8843 | 35U | | E95 | 269.02 |
| 132-12 | 811212 | 8843 | 3RU | | E24 | 403.02 |
| 132-12 | 811212 | 8843 | 3RU | | E95 | 269.02 |
| 132-12 | 811212 | 8843 | 55U | | E24 | 403.02 |
| 132-12 | 811212 | 8843 | 55U | | E95 | 269.02 |
| 132-12 | 811212 | 8843 | AC1 | | E24 | 403.02 |
| 132-12 | 811212 | 8843 | AC1 | | E95 | 269.02 |
| 132-12 | 811212 | 8843 | MC1 | | E24 | 403.02 |
| 132-12 | 811212 | 8843 | MC1 | | E95 | 269.02 |
| 132-12 | 811212 | 8844 | AC1 | | E24 | 403.02 |
| 132-12 | 811212 | 8844 | AC1 | | E95 | 269.02 |
| 132-12 | 811212 | 8849 | AC1 | | E24 | 503.78 |

| | | | | | | |
|--------|--------|------|-----|--|-----|---------|
| 132-12 | 811212 | 8849 | MC1 | | E24 | 503.78 |
| 132-12 | 811212 | 8850 | AC1 | | E24 | 403.02 |
| 132-12 | 811212 | 8850 | MC1 | | E24 | 403.02 |
| 132-12 | 811212 | 8852 | 4XU | | E24 | 685.14 |
| 132-12 | 811212 | 8852 | 4XU | | E95 | 456.42 |
| 132-12 | 811212 | 8852 | HC1 | | E24 | 685.14 |
| 132-12 | 811212 | 8853 | AC1 | | E24 | 403.02 |
| 132-12 | 811212 | 8853 | MC1 | | E24 | 403.02 |
| 132-12 | 811212 | 8863 | AC1 | | E24 | 740.55 |
| 132-12 | 811212 | 8863 | MC1 | | E24 | 740.55 |
| 132-12 | 811212 | 8865 | AC1 | | E24 | 1511.34 |
| 132-12 | 811212 | 8865 | MC1 | | E24 | 1511.34 |
| 132-12 | 811212 | 8866 | AC1 | | E24 | 1511.34 |
| 132-12 | 811212 | 8866 | MC1 | | E24 | 1511.34 |
| 132-12 | 811212 | 8872 | AC1 | | E24 | 3627.2 |
| 132-12 | 811212 | 8872 | MC1 | | E24 | 3627.2 |
| 132-12 | 811212 | 8874 | AC1 | | E24 | 1813.6 |
| 132-12 | 811212 | 8874 | MC1 | | E24 | 1813.6 |
| 132-12 | 811212 | 8877 | AC1 | | E24 | 806.05 |
| 132-12 | 811212 | 8877 | MC1 | | E24 | 806.05 |
| 132-12 | 811212 | 8886 | AC1 | | E24 | 1511.34 |
| 132-12 | 811212 | 9228 | AC1 | | E95 | 200.5 |
| 132-12 | 811212 | 9228 | MC1 | | E95 | 200.5 |
| 132-12 | 811212 | 9306 | RC1 | | E24 | 446.35 |
| 132-12 | 811212 | 9307 | RC2 | | E24 | 446.35 |
| 132-12 | 811212 | 9307 | RC4 | | E24 | 446.35 |
| 132-12 | 811212 | 9308 | 42E | | E24 | 460.45 |
| 132-12 | 811212 | 9308 | 42S | | E24 | 460.45 |
| 132-12 | 811212 | 9308 | RC4 | | E24 | 460.45 |
| 132-12 | 811212 | 9512 | AB0 | | E95 | 130.98 |

| SIN | 811212 | MFR PART NO | PRODUCT DESCRIPTION | GSA PRICE |
|------------|---------------|--------------------|---|------------------|
| 132-12 | 811212 | BVQSM1-2yr | BVQ for SVC Base Edition Tier 1 2yr maintenance | \$206.74 |
| 132-12 | 811212 | BVQSM1-3yr | BVQ for SVC Base Edition Tier 1 3yr maintenance | \$310.11 |
| 132-12 | 811212 | BVQSM1-3yr | BVQ for SVC Base Edition Tier 1 3yr maintenance | \$310.11 |
| 132-12 | 811212 | BVQSM1-4yr | BVQ for SVC Base Edition Tier 1 4yr maintenance | \$413.48 |
| 132-12 | 811212 | BVQSM2-2yr | BVQ for SVC Base Edition Tier 2 2yr maintenance | \$165.39 |
| 132-12 | 811212 | BVQSM2-3yr | BVQ for SVC Base Edition Tier 2 3yr maintenance | \$248.09 |

| | | | | |
|--------|--------|------------|---|----------|
| 132-12 | 811212 | BVQSM2-4yr | BVQ for SVC Base Edition Tier 2 4yr maintenance | \$330.78 |
| 132-12 | 811212 | BVQSM3-2yr | BVQ for SVC Base Edition Tier 3 2yr maintenance | \$165.39 |
| 132-12 | 811212 | BVQSM3-3yr | BVQ for SVC Base Edition Tier 3 3yr maintenance | \$248.09 |
| 132-12 | 811212 | BVQSM3-4yr | BVQ for SVC Base Edition Tier 3 4yr maintenance | \$330.78 |
| 132-12 | 811212 | BVQSM4-2yr | BVQ for SVC Base Edition Tier 4 2yr maintenance | \$82.70 |
| 132-12 | 811212 | BVQSM4-3yr | BVQ for SVC Base Edition Tier 4 3yr maintenance | \$124.04 |
| 132-12 | 811212 | BVQSM4-4yr | BVQ for SVC Base Edition Tier 4 4yr maintenance | \$165.39 |
| 132-12 | 811212 | BVQSM5-2yr | BVQ for SVC Base Edition Tier 5 2yr maintenance | \$74.43 |
| 132-12 | 811212 | BVQSM5-3yr | BVQ for SVC Base Edition Tier 5 3yr maintenance | \$111.64 |
| 132-12 | 811212 | BVQSM5-4yr | BVQ for SVC Base Edition Tier 5 4yr maintenance | \$148.85 |
| 132-12 | 811212 | BVQSM6-2yr | BVQ for SVC Base Edition Tier 6 2yr maintenance | \$62.02 |
| 132-12 | 811212 | BVQSM6-3yr | BVQ for SVC Base Edition Tier 6 3yr maintenance | \$93.03 |
| 132-12 | 811212 | BVQSM6-4yr | BVQ for SVC Base Edition Tier 6 4yr maintenance | \$124.04 |
| 132-12 | 811212 | BVQSM7-2yr | BVQ for SVC Base Edition Tier 7 2yr maintenance | \$49.62 |
| 132-12 | 811212 | BVQSM7-3yr | BVQ for SVC Base Edition Tier 7 3yr maintenance | \$74.43 |
| 132-12 | 811212 | BVQSM7-4yr | BVQ for SVC Base Edition Tier 7 4yr maintenance | \$99.23 |
| 132-12 | 811212 | BVQSM8-2yr | BVQ for SVC Base Edition Tier 8 2yr maintenance | \$41.35 |
| 132-12 | 811212 | BVQSM8-3yr | BVQ for SVC Base Edition Tier 8 3yr maintenance | \$62.02 |
| 132-12 | 811212 | BVQSM8-4yr | BVQ for SVC Base Edition Tier 8 4yr maintenance | \$82.70 |

| | | | | |
|--------|--------|--------------|---|---------|
| 132-12 | 811212 | BVQSM-A1-2yr | BVQ Accounting Package Tier 1 2yr maintenance | \$28.00 |
| 132-12 | 811212 | BVQSM-A1-3yr | BVQ Accounting Package Tier 1 3yr maintenance | \$42.00 |
| 132-12 | 811212 | BVQSM-A1-4yr | BVQ Accounting Package Tier 1 4yr maintenance | \$55.99 |
| 132-12 | 811212 | BVQSM-A2-2yr | BVQ Accounting Package Tier 2 2yr maintenance | \$25.84 |
| 132-12 | 811212 | BVQSM-A2-3yr | BVQ Accounting Package Tier 2 3yr maintenance | \$38.76 |
| 132-12 | 811212 | BVQSM-A2-4yr | BVQ Accounting Package Tier 2 4yr maintenance | \$51.68 |
| 132-12 | 811212 | BVQSM-A3-2yr | BVQ Accounting Package Tier 3 2yr maintenance | \$16.37 |
| 132-12 | 811212 | BVQSM-A3-3yr | BVQ Accounting Package Tier 3 3yr maintenance | \$24.55 |
| 132-12 | 811212 | BVQSM-A3-4yr | BVQ Accounting Package Tier 3 4yr maintenance | \$32.73 |
| 132-12 | 811212 | BVQSM-A4-2yr | BVQ Accounting Package Tier 4 2yr maintenance | \$12.92 |
| 132-12 | 811212 | BVQSM-A4-3yr | BVQ Accounting Package Tier 4 3yr maintenance | \$19.38 |
| 132-12 | 811212 | BVQSM-A4-4yr | BVQ Accounting Package Tier 4 4yr maintenance | \$25.84 |
| 132-12 | 811212 | BVQSM-A5-2yr | BVQ Accounting Package Tier 5 2yr maintenance | \$9.93 |
| 132-12 | 811212 | BVQSM-A5-3yr | BVQ Accounting Package Tier 5 3yr maintenance | \$14.87 |
| 132-12 | 811212 | BVQSM-A5-4yr | BVQ Accounting Package Tier 5 4yr maintenance | \$19.83 |
| 132-12 | 811212 | BVQSM-A6-2yr | BVQ Accounting Package Tier 6 2yr maintenance | \$8.19 |
| 132-12 | 811212 | BVQSM-A6-3yr | BVQ Accounting Package Tier 6 3yr maintenance | \$12.29 |
| 132-12 | 811212 | BVQSM-A6-4yr | BVQ Accounting Package Tier 6 4yr maintenance | \$16.39 |
| 132-12 | 811212 | BVQSM-A7-2yr | BVQ Accounting Package Tier 7 2yr maintenance | \$7.75 |

| | | | | |
|--------|--------|--------------|---|---------|
| 132-12 | 811212 | BVQSM-A7-3yr | BVQ Accounting Package Tier 7 3yr maintenance | \$11.63 |
| 132-12 | 811212 | BVQSM-A7-4yr | BVQ Accounting Package Tier 7 4yr maintenance | \$15.51 |
| 132-12 | 811212 | BVQSM-A8-2yr | BVQ Accounting Package Tier 8 2yr maintenance | \$5.61 |
| 132-12 | 811212 | BVQSM-A8-3yr | BVQ Accounting Package Tier 8 3yr maintenance | \$8.41 |
| 132-12 | 811212 | BVQSM-A8-4yr | BVQ Accounting Package Tier 8 4yr maintenance | \$11.22 |
| 132-12 | 811212 | BVQSL-S1 | BVQ Service Level Management Package Tier 1 | \$62.21 |
| 132-12 | 811212 | BVQSL-S2 | BVQ Service Level Management Package Tier 2 | \$57.43 |
| 132-12 | 811212 | BVQSL-S3 | BVQ Service Level Management Package Tier 3 | \$36.37 |
| 132-12 | 811212 | BVQSL-S4 | BVQ Service Level Management Package Tier 4 | \$28.71 |
| 132-12 | 811212 | BVQSL-S5 | BVQ Service Level Management Package Tier 5 | \$22.01 |
| 132-12 | 811212 | BVQSL-S6 | BVQ Service Level Management Package Tier 6 | \$18.19 |
| 132-12 | 811212 | BVQSL-S7 | BVQ Service Level Management Package Tier 7 | \$17.23 |
| 132-12 | 811212 | BVQSL-S8 | BVQ Service Level Management Package Tier 8 | \$12.44 |
| 132-12 | 811212 | BVQSM-S1-2yr | BVQ Service Level Management Package Tier 1 2yr maintenance | \$28.00 |
| 132-12 | 811212 | BVQSM-S1-3yr | BVQ Service Level Management Package Tier 1 3yr maintenance | \$42.00 |
| 132-12 | 811212 | BVQSM-S1-4yr | BVQ Service Level Management Package Tier 1 4yr maintenance | \$55.99 |
| 132-12 | 811212 | BVQSM-S2-2yr | BVQ Service Level Management Package Tier 2 2yr maintenance | \$25.84 |

| | | | | |
|--------|--------|--------------|---|---------|
| 132-12 | 811212 | BVQSM-S2-3yr | BVQ Service Level Management Package Tier 2 3yr maintenance | \$38.76 |
| 132-12 | 811212 | BVQSM-S2-4yr | BVQ Service Level Management Package Tier 2 4yr maintenance | \$51.68 |
| 132-12 | 811212 | BVQSM-S3-2yr | BVQ Service Level Management Package Tier 3 2yr maintenance | \$16.37 |
| 132-12 | 811212 | BVQSM-S3-3yr | BVQ Service Level Management Package Tier 3 3yr maintenance | \$24.55 |
| 132-12 | 811212 | BVQSM-S3-4yr | BVQ Service Level Management Package Tier 3 4yr maintenance | \$32.73 |
| 132-12 | 811212 | BVQSM-S4-2yr | BVQ Service Level Management Package Tier 3 2yr maintenance | \$12.92 |
| 132-12 | 811212 | BVQSM-S4-3yr | BVQ Service Level Management Package Tier 4 3yr maintenance | \$19.38 |
| 132-12 | 811212 | BVQSM-S4-4yr | BVQ Service Level Management Package Tier 4 4yr maintenance | \$25.84 |
| 132-12 | 811212 | BVQSM-S5-2yr | BVQ Service Level Management Package Tier 5 2yr maintenance | \$9.93 |
| 132-12 | 811212 | BVQSM-S5-3yr | BVQ Service Level Management Package Tier 5 3yr maintenance | \$14.87 |
| 132-12 | 811212 | BVQSM-S5-4yr | BVQ Service Level Management Package Tier 5 4yr maintenance | \$19.83 |
| 132-12 | 811212 | BVQSM-S6-2yr | BVQ Service Level Management Package Tier 6 2yr maintenance | \$8.19 |
| 132-12 | 811212 | BVQSM-S6-3yr | BVQ Service Level Management Package Tier 6 3yr maintenance | \$12.29 |
| 132-12 | 811212 | BVQSM-S6-4yr | BVQ Service Level Management Package Tier 6 4yr maintenance | \$16.39 |

| | | | | |
|--------|--------|--------------|---|---------|
| 132-12 | 811212 | BVQSM-S7-2yr | BVQ Service Level Management Package Tier 7 2yr maintenance | \$7.75 |
| 132-12 | 811212 | BVQSM-S7-3yr | BVQ Service Level Management Package Tier 7 3yr maintenance | \$11.63 |
| 132-12 | 811212 | BVQSM-S7-4yr | BVQ Service Level Management Package Tier 7 4yr maintenance | \$15.51 |
| 132-12 | 811212 | BVQSM-S8-2yr | BVQ Service Level Management Package Tier 8 2yr maintenance | \$5.61 |
| 132-12 | 811212 | BVQSM-S8-3yr | BVQ Service Level Management Package Tier 8 3yr maintenance | \$8.41 |
| 132-12 | 811212 | BVQSM-S8-4yr | BVQ Service Level Management Package Tier 8 4yr maintenance | \$11.22 |
| 132-12 | 811212 | BVQSM-V1-2yr | BVQ Vmware Package Tier 1 2yr maintenance | \$28.00 |
| 132-12 | 811212 | BVQSM-V1-3yr | BVQ Vmware Package Tier 1 3yr maintenance | \$42.00 |
| 132-12 | 811212 | BVQSM-V1-4yr | BVQ Vmware Package Tier 1 4yr maintenance | \$55.99 |
| 132-12 | 811212 | BVQSM-V2-2yr | BVQ Vmware Package Tier 2 2yr maintenance | \$25.84 |
| 132-12 | 811212 | BVQSM-V2-3yr | BVQ Vmware Package Tier 2 3yr maintenance | \$38.76 |
| 132-12 | 811212 | BVQSM-V2-4yr | BVQ Vmware Package Tier 2 4yr maintenance | \$51.68 |
| 132-12 | 811212 | BVQSM-V3-2yr | BVQ Vmware Package Tier 3 2yr maintenance | \$16.37 |
| 132-12 | 811212 | BVQSM-V3-3yr | BVQ Vmware Package Tier 3 3yr maintenance | \$24.55 |
| 132-12 | 811212 | BVQSM-V3-4yr | BVQ Vmware Package Tier 3 4yr maintenance | \$32.73 |
| 132-12 | 811212 | BVQSM-V4-2yr | BVQ Vmware Package Tier 4 2yr maintenance | \$12.92 |
| 132-12 | 811212 | BVQSM-V4-3yr | BVQ Vmware Package Tier 4 3yr maintenance | \$19.38 |

| | | | | |
|--------|--------|--------------|--|---------|
| 132-12 | 811212 | BVQSM-V4-4yr | BVQ Vmware Package Tier 4 4yr maintenance | \$25.84 |
| 132-12 | 811212 | BVQSM-V5-2yr | BVQ Vmware Package Tier 5 2yr maintenance | \$9.93 |
| 132-12 | 811212 | BVQSM-V5-3yr | BVQ Vmware Package Tier 5 3yr maintenance | \$14.87 |
| 132-12 | 811212 | BVQSM-V5-4yr | BVQ Vmware Package Tier 5 4yr maintenance | \$19.83 |
| 132-12 | 811212 | BVQSM-V6-2yr | BVQ Vmware Package Tier 6 2yr maintenance | \$8.19 |
| 132-12 | 811212 | BVQSM-V6-3yr | BVQ Vmware Package Tier 6 3yr maintenance | \$12.29 |
| 132-12 | 811212 | BVQSM-V6-4yr | BVQ Vmware Package Tier 6 4yr maintenance | \$16.39 |
| 132-12 | 811212 | BVQSM-V7-2yr | BVQ Vmware Package Tier 7 2yr maintenance | \$7.75 |
| 132-12 | 811212 | BVQSM-V7-3yr | BVQ Vmware Package Tier 7 3yr maintenance | \$11.63 |
| 132-12 | 811212 | BVQSM-V7-4yr | BVQ Vmware Package Tier 7 4yr maintenance | \$15.51 |
| 132-12 | 811212 | BVQSM-V8-2yr | BVQ Vmware Package Tier 8 2yr maintenance | \$5.61 |
| 132-12 | 811212 | BVQSM-V8-3yr | BVQ Vmware Package Tier 8 3yr maintenance | \$8.41 |
| 132-12 | 811212 | BVQSM-V8-4yr | BVQ Vmware Package Tier 8 4yr maintenance | \$11.22 |
| 132-12 | 811212 | BVQSM-C1-2yr | BVQ Copy Services Package Tier 1 2yr maintenance | \$28.00 |
| 132-12 | 811212 | BVQSM-C1-3yr | BVQ Copy Services Package Tier 1 3yr maintenance | \$42.00 |
| 132-12 | 811212 | BVQSM-C1-4yr | BVQ Copy Services Package Tier 1 3yr maintenance | \$55.99 |
| 132-12 | 811212 | BVQSM-C2-2yr | BVQ Copy Services Package Tier 2 2yr maintenance | \$25.84 |
| 132-12 | 811212 | BVQSM-C2-3yr | BVQ Copy Services Package Tier 2 3yr maintenance | \$38.76 |
| 132-12 | 811212 | BVQSM-C2-4yr | BVQ Copy Services Package Tier 2 3yr maintenance | \$51.68 |

| | | | | |
|--------|--------|--------------|---|---------|
| 132-12 | 811212 | BVQSM-C3-2yr | BVQ Copy Services Package Tier 3 2yr maintenance | \$16.37 |
| 132-12 | 811212 | BVQSM-C3-3yr | BVQ Copy Services Package Tier 3 3yr maintenance | \$24.55 |
| 132-12 | 811212 | BVQSM-C3-4yr | BVQ Copy Services Package Tier 3 3yr maintenance | \$32.73 |
| 132-12 | 811212 | BVQSM-C4-2yr | BVQ Copy Services Package Tier 4 2yr maintenance | \$12.92 |
| 132-12 | 811212 | BVQSM-C4-3yr | BVQ Copy Services Package Tier 4 3yr maintenance | \$19.38 |
| 132-12 | 811212 | BVQSM-C4-4yr | BVQ Copy Services Package Tier 4 3yr maintenance | \$25.84 |
| 132-12 | 811212 | BVQSM-C5-2yr | BVQ Copy Services Package Tier 5 2yr maintenance | \$9.93 |
| 132-12 | 811212 | BVQSM-C5-3yr | BVQ Copy Services Package Tier 5 3yr maintenance | \$14.87 |
| 132-12 | 811212 | BVQSM-C5-4yr | BVQ Copy Services Package Tier 5 3yr maintenance | \$19.83 |
| 132-12 | 811212 | BVQSM-C6-2yr | BVQ Copy Services Package Tier 6 2yr maintenance | \$8.19 |
| 132-12 | 811212 | BVQSM-C6-3yr | BVQ Copy Services Package Tier 6 3yr maintenance | \$12.29 |
| 132-12 | 811212 | BVQSM-C6-4yr | BVQ Copy Services Package Tier 6 3yr maintenance | \$16.39 |
| 132-12 | 811212 | BVQSM-C7-2yr | BVQ Copy Services Package Tier 7 2yr maintenance | \$7.75 |
| 132-12 | 811212 | BVQSM-C7-3yr | BVQ Copy Services Package Tier 7 3yr maintenance | \$11.63 |
| 132-12 | 811212 | BVQSM-C7-4yr | BVQ Copy Services Package Tier 7 3yr maintenance | \$15.51 |
| 132-12 | 811212 | BVQSM-C8-2yr | BVQ Copy Services Package Tier 8 2yr maintenance | \$5.61 |
| 132-12 | 811212 | BVQSM-C8-3yr | BVQ Copy Services Package Tier 8 3yr maintenance | \$8.41 |
| 132-12 | 811212 | BVQSM-C8-4yr | BVQ Copy Services Package Tier 8 3yr maintenance | \$11.22 |
| 132-12 | 811212 | BVQSM-F1-2yr | BVQ Fabric Network Package Tier 1 2yr maintenance | \$28.00 |

| | | | | |
|--------|--------|--------------|---|---------|
| 132-12 | 811212 | BVQSM-F1-3yr | BVQ Fabric Network Package Tier 1 3yr maintenance | \$42.00 |
| 132-12 | 811212 | BVQSM-F1-4yr | BVQ Fabric Network Package Tier 1 3yr maintenance | \$55.99 |
| 132-12 | 811212 | BVQSM-F2-2yr | BVQ Fabric Network Package Tier 2 2yr maintenance | \$25.84 |
| 132-12 | 811212 | BVQSM-F2-3yr | BVQ Fabric Network Package Tier 2 3yr maintenance | \$38.76 |
| 132-12 | 811212 | BVQSM-F2-4yr | BVQ Fabric Network Package Tier 2 3yr maintenance | \$51.68 |
| 132-12 | 811212 | BVQSM-F3-2yr | BVQ Fabric Network Package Tier 3 2yr maintenance | \$16.37 |
| 132-12 | 811212 | BVQSM-F3-3yr | BVQ Fabric Network Package Tier 3 3yr maintenance | \$24.55 |
| 132-12 | 811212 | BVQSM-F3-4yr | BVQ Fabric Network Package Tier 3 3yr maintenance | \$32.73 |
| 132-12 | 811212 | BVQSM-F4-2yr | BVQ Fabric Network Package Tier 4 2yr maintenance | \$12.92 |
| 132-12 | 811212 | BVQSM-F4-3yr | BVQ Fabric Network Package Tier 4 3yr maintenance | \$19.38 |
| 132-12 | 811212 | BVQSM-F4-4yr | BVQ Fabric Network Package Tier 4 3yr maintenance | \$25.84 |
| 132-12 | 811212 | BVQSM-F5-2yr | BVQ Fabric Network Package Tier 5 2yr maintenance | \$9.93 |
| 132-12 | 811212 | BVQSM-F5-3yr | BVQ Fabric Network Package Tier 5 3yr maintenance | \$14.87 |
| 132-12 | 811212 | BVQSM-F5-4yr | BVQ Fabric Network Package Tier 5 3yr maintenance | \$19.83 |
| 132-12 | 811212 | BVQSM-F6-2yr | BVQ Fabric Network Package Tier 6 2yr maintenance | \$8.19 |
| 132-12 | 811212 | BVQSM-F6-3yr | BVQ Fabric Network Package Tier 6 3yr maintenance | \$12.29 |
| 132-12 | 811212 | BVQSM-F6-4yr | BVQ Fabric Network Package Tier 6 3yr maintenance | \$16.39 |
| 132-12 | 811212 | BVQSM-F7-2yr | BVQ Fabric Network Package Tier 7 2yr maintenance | \$7.75 |
| 132-12 | 811212 | BVQSM-F7-3yr | BVQ Fabric Network Package Tier 7 3yr maintenance | \$11.63 |

| | | | | |
|--------|--------|---------------|---|------------|
| 132-12 | 811212 | BVQSM-F7-4yr | BVQ Fabric Network Package Tier 7 3yr maintenance | \$15.51 |
| 132-12 | 811212 | BVQSM-F8-2yr | BVQ Fabric Network Package Tier 8 2yr maintenance | \$5.61 |
| 132-12 | 811212 | BVQSM-F8-3yr | BVQ Fabric Network Package Tier 8 3yr maintenance | \$8.41 |
| 132-12 | 811212 | BVQSM-F8-4yr | BVQ Fabric Network Package Tier 8 3yr maintenance | \$11.22 |
| 132-12 | 811212 | BVQ75M1-1yr | BVQ for Storwize V7,V5 Base Edition 1yr maintenance per Enclosure | \$1,076.77 |
| 132-12 | 811212 | BVQ75M1-2yr | BVQ for Storwize V7,V5 Base Edition 2yr maintenance per Enclosure | \$2,153.53 |
| 132-12 | 811212 | BVQ75M1-3yr | BVQ for Storwize V7,V5 Base Edition 3yr maintenance per Enclosure | \$3,230.30 |
| 132-12 | 811212 | BVQ75M1-4yr | BVQ for Storwize V7,V5 Base Edition 4yr maintenance per Enclosure | \$4,307.06 |
| 132-12 | 811212 | BVQ75M-A1-1yr | BVQ for Storwize V7,V5 Accounting Package 1yr maintenance per Enclosure | \$134.00 |
| 132-12 | 811212 | BVQ75M-A1-2yr | BVQ for Storwize V7,V5 Accounting Package 2yr maintenance per Enclosure | \$268.00 |
| 132-12 | 811212 | BVQ75M-A1-3yr | BVQ for Storwize V7,V5 Accounting Package 3yr maintenance per Enclosure | \$401.99 |
| 132-12 | 811212 | BVQ75M-A1-4yr | BVQ for Storwize V7,V5 Accounting Package 4yr maintenance per Enclosure | \$535.99 |
| 132-12 | 811212 | BVQ75M-S1-1yr | BVQ for Storwize V7,V5 Service Level Management Package 1yr maintenance per Enclosure | \$134.00 |

| | | | | |
|--------|--------|---------------|---|----------|
| 132-12 | 811212 | BVQ75M-S1-2yr | BVQ for Storwize V7,V5 Service Level Management Package 2yr maintenance per Enclosure | \$268.00 |
| 132-12 | 811212 | BVQ75M-S1-3yr | BVQ for Storwize V7,V5 Service Level Management Package 3yr maintenance per Enclosure | \$401.99 |
| 132-12 | 811212 | BVQ75M-S1-4yr | BVQ for Storwize V7,V5 Service Level Management Package 4yr maintenance per Enclosure | \$535.99 |
| 132-12 | 811212 | BVQ75M-V1-1yr | BVQ for Storwize V7,V5 Vmware Package 1yr maintenance per Enclosure | \$134.00 |
| 132-12 | 811212 | BVQ75M-V1-2yr | BVQ for Storwize V7,V5 Vmware Package 2yr maintenance per Enclosure | \$268.00 |
| 132-12 | 811212 | BVQ75M-V1-3yr | BVQ for Storwize V7,V5 Vmware Package 3yr maintenance per Enclosure | \$401.99 |
| 132-12 | 811212 | BVQ75M-V1-4yr | BVQ for Storwize V7,V5 Vmware Package 4yr maintenance per Enclosure | \$535.99 |
| 132-12 | 811212 | BVQ75M-C1-1yr | BVQ for Storwize V7,V5 Copy Services Package 1yr maintenance per Enclosure | \$134.00 |
| 132-12 | 811212 | BVQ75M-C1-2yr | BVQ for Storwize V7,V5 Copy Services Package 2yr maintenance per Enclosure | \$268.00 |
| 132-12 | 811212 | BVQ75M-C1-3yr | BVQ for Storwize V7,V5 Copy Services Package 3yr maintenance per Enclosure | \$401.99 |
| 132-12 | 811212 | BVQ75M-C1-4yr | BVQ for Storwize V7,V5 Copy Services Package 4yr maintenance per Enclosure | \$535.99 |

| | | | | |
|--------|--------|---------------|---|------------|
| 132-12 | 811212 | BVQ75M-F1-1yr | BVQ for Storwize V7,V5 Fabric Network Package 1yr maintenance per Enclosure | \$134.00 |
| 132-12 | 811212 | BVQ75M-F1-2yr | BVQ for Storwize V7,V5 Fabric Network Package 2yr maintenance per Enclosure | \$268.00 |
| 132-12 | 811212 | BVQ75M-F1-3yr | BVQ for Storwize V7,V5 Fabric Network Package 3yr maintenance per Enclosure | \$401.99 |
| 132-12 | 811212 | BVQ75M-F1-4yr | BVQ for Storwize V7,V5 Fabric Network Package 4yr maintenance per Enclosure | \$535.99 |
| 132-12 | 811212 | BVQ3M1-1yr | BVQ for Storwize V3700 Base Edition 1yr maintenance per system | \$538.38 |
| 132-12 | 811212 | BVQ3M1-2yr | BVQ for Storwize V3700 Base Edition 2yr maintenance per system | \$1,076.77 |
| 132-12 | 811212 | BVQ3M1-3yr | BVQ for Storwize V3700 Base Edition 3yr maintenance per system | \$1,615.15 |
| 132-12 | 811212 | BVQ3M1-4yr | BVQ for Storwize V3700 Base Edition 4yr maintenance per system | \$2,153.53 |
| 132-12 | 811212 | BVQ3M-A1-1yr | BVQ for Storwize V3700Accounting Package 1yr maintenance per system | \$134.00 |
| 132-12 | 811212 | BVQ3M-A1-2yr | BVQ for Storwize V3700 Accounting Package 2yr maintenance per system | \$268.00 |
| 132-12 | 811212 | BVQ3M-A1-3yr | BVQ for Storwize V3700 Accounting Package 3yr maintenance per system | \$401.99 |
| 132-12 | 811212 | BVQ3M-A1-4yr | BVQ for Storwize V3700 Accounting Package 4yr maintenance per system | \$535.99 |

| | | | | |
|--------|--------|--------------|--|----------|
| 132-12 | 811212 | BVQ3M-S1-1yr | BVQ for Storwize V3700 Service Level Management Package 1yr maintenance per system | \$134.00 |
| 132-12 | 811212 | BVQ3M-S1-2yr | BVQ for Storwize V3700 Service Level Management Package 2yr maintenance per system | \$268.00 |
| 132-12 | 811212 | BVQ3M-S1-3yr | BVQ for Storwize V3700 Service Level Management Package 3yr maintenance per system | \$401.99 |
| 132-12 | 811212 | BVQ3M-S1-4yr | BVQ for Storwize V3700 Service Level Management Package 4yr maintenance per system | \$535.99 |
| 132-12 | 811212 | BVQ3M-V1-1yr | BVQ for Storwize V3700 VMware Package 1yr maintenance per system | \$134.00 |
| 132-12 | 811212 | BVQ3M-V1-2yr | BVQ for Storwize V3700 VMware Package 2yr maintenance per system | \$268.00 |
| 132-12 | 811212 | BVQ3M-V1-3yr | BVQ for Storwize V3700 VMware Package 3yr maintenance per system | \$401.99 |
| 132-12 | 811212 | BVQ3M-V1-4yr | BVQ for Storwize V3700 VMware Package 4yr maintenance per system | \$535.99 |
| 132-12 | 811212 | BVQ3M-C1-1yr | BVQ for Storwize V3700 Copy Services Package 1yr maintenance per system | \$134.00 |
| 132-12 | 811212 | BVQ3M-C1-2yr | BVQ for Storwize V3700 Copy Services Package 2yr maintenance per system | \$268.00 |

| | | | | |
|--------|--------|--------------|--|----------|
| 132-12 | 811212 | BVQ3M-C1-3yr | BVQ for Storwize V3700 Copy Services Package 3yr maintenance per system | \$401.99 |
| 132-12 | 811212 | BVQ3M-C1-4yr | BVQ for Storwize V3700 Copy Services Package 4yr maintenance per system | \$535.99 |
| 132-12 | 811212 | BVQ3M-F1-1yr | BVQ for Storwize V3700 Fabric Network Package 1yr maintenance per system | \$134.00 |
| 132-12 | 811212 | BVQ3M-F1-2yr | BVQ for Storwize V3700 Fabric Network Package 2yr maintenance per system | \$268.00 |
| 132-12 | 811212 | BVQ3M-F1-3yr | BVQ for Storwize V3700 Fabric Network Package 3yr maintenance per system | \$401.99 |
| 132-12 | 811212 | BVQ3M-F1-4yr | BVQ for Storwize V3700 Fabric Network Package 4yr maintenance per system | \$535.99 |